

87 GFF test plan required for A/C compressor replacements regardless of concern

87 19 91 2041717/6 June 21, 2019. Supersedes Technical Service Bulletin Group 87 number 18-87 dated July 25, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All except Audi e-tron quattro	2010 - 2021	All	Not Applicable

Condition

REVISION HISTORY						
Revision	Date	Purpose				
6	-	Revised header (Removed Audi e-tron quattro)				
5	07/25/2018	Revised header (Added MY2019 - 2021 vehicles) Revised Service (Updated Note)				
4	11/17/2016	Revised Service (Clarification of test plan location in ODIS) Revised Additional Information (Added reference)				

This bulletin applies to any repair that requires replacement of the air conditioning compressor.

Technical Background

Any replacement of A/C compressors—regardless of the reason for failure—must include an ODIS GFF cooling performance test plan (Function Test Log version) of the A/C system with documentation of the recovered refrigerant volume. This GFF test plan requirement is mandatory without exception.

Production Solution

Not applicable.




Service

Before replacing the A/C compressor, run the ODIS GFF test plan. The test plan is in various locations in the navigation depending on the vehicle being serviced. Since the A/C cooling performance test is a 'function test' it is generally found by navigating to sub-headers such as 'functions', 'other functions' or 'general function tests' in Heating and Air Conditioning Electronics. The following are two examples.

2017 Q7 (with 3-zone climate control):

1. Navigate to the Test plan tab of the diagnosis program (Figure 1). Select Body >> Heating / Air Conditioning >> 01 – On Board Diagnostic (OBD) capable systems >> 08 – Front A/C display control head –E87- >> 08 Heating/Air Conditioning Electronics, functions >> 08-Other Functions.










Figure 1. Cooling performance test plan navigation on a 2017 Q7 with 3-zone climate control.

2017 Q3:



 Navigate to the Test plan tab of the diagnosis program (Figure 2). Select Body >> Heating / Air Conditioning >> 01 – On Board Diagnostic (OBD) capable systems >> 08 Climatronic control module, functions J255 >> 08-General function tests.





Page 4 of 7






Figure 2. Cooling performance test plan navigation on a 2017 Q3.

- 3. Once the function test has been added to the list of "Tests in current test plan" select "Vehicle is not cooling".
- 4. The cooling system performance test plan can then be completed following the prompts.
- 5. If the A/C performance test returns "No malfunctions", then no repairs are needed. The system is operating properly.

If the A/C performance test returns a malfunction, perform diagnosis and repair the system as needed. If the compressor is found to be faulty according to the test plan and is replaced please:

- Upload the "Long" version of the Diagnostic Log to GFF Paperless. It is not necessary to print this
 version
- Print out and attach the "Function Test" version of the diagnostic log to the replaced compressor for return to the WPRC (Figure 3). It is not necessary to print and attach the "Long" version of the diagnostic log.






Figure 3. Only print a copy of the Function test version of the diagnostic log and attach to the replaced compressor.

6. **Note:**

As previously mentioned the cooling performance test plan is in various locations in the navigation depending on the vehicle and equipment level. This variation in test plan location <u>does not in any way</u> waive the requirement for this test plan to be run before an air conditioning compressor is replaced. If the test plan is missing or cannot be found in ODIS please file an ODIS Feedback. Consult the Technical Assistance Center (TACS) for assistance, if necessary, before replacing an air conditioning compressor without a GFF test plan supporting the replacement.

UNote:

All other applicable bulletins apply. See TSB 2035582: 87 A/C compressor replacement for information on required documentation of recovered refrigerant volume up to and including MY2017.



Warranty

Claim Type:	 110 up to 48 Months/50,000 Miles. G10 for CPO Covered Vehicles – Verify Owner. If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 					
Service Number:	8734					
Damage Code:	0016					
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 100 TU)			
	Road test prior to service procedure	No allowance	0 TU			
	Road test after service procedure	No allowance	0 TU			
Claim Comment:	As per TSB #2041717/6					

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

• TSB 2035582, 87 A/C compressor replacement.

All parts and service references provided in this TSB (2041717) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.