

- ATTENTION:**
- GENERAL MANAGER
 - PARTS MANAGER
 - CLAIMS PERSONNEL
 - SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

©2018 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

PRODUCT CAMPAIGN BULLETIN

APPLICABILITY: 2010-2014 MY Legacy and Outback (M/T models) **NUMBER:** **WTV-81R**
SUBJECT: Electronic Parking Brake (EPB) Actuator **NHTSA ID:** 18V-626
INTRODUCTION: **DATE:** 10/30/18
REVISED: 06/14/19

Subaru of America, Inc. (Subaru) is recalling all 2010-2014 model year Legacy and Outback vehicles equipped with a manual transmission (M/T), to replace the electronic parking brake (EPB) actuator assembly. A total of 27,175 U.S. vehicles are affected by this recall.

Vehicles equipped with an automatic transmission are not affected by this recall. However, they will be covered under an extended warranty. Details of the extended warranty coverage will be forthcoming.

AFFECTED VEHICLES:

Model Year	Carline	Production Range
2010-2014	Legacy equipped with M/T	All M/T
2010-2014	Outback equipped with M/T	All M/T

NOTE: Remedy parts are not yet available. The status of this recall will display as “Open – Remedy Not Yet Available” until remedy parts become available. Until parts are available, this recall cannot be performed.

Coverage for all affected vehicles must be confirmed by using the Vehicle Coverage Inquiry function on subarunet.com. This information is available.

DESCRIPTION OF THE ISSUE AND SAFETY RISK:

Due to improper manufacturing processes, a capacitor on the circuit board and/or the actuator stroke sensor magnetic ring located in the control unit of the EPB may crack over time. If either component develops a crack, the brake telltale warning lamp will illuminate, and the EPB may not apply as intended.

If the manual transmission (M/T) shift lever is not in the recommended gear when the vehicle is parked and the EPB does not engage, the vehicle may roll away, increasing the risk of a crash.

Continued...

<p>CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.</p> <p>Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.</p>	<p style="text-align: center;">Subaru of America, Inc. is ISO 14001 Compliant</p> <p>ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.</p>
--	--

DESCRIPTION OF THE REMEDY:

Once parts are available, the EPB actuator assembly will be replaced on all 2010-2014 model year Legacy and Outback vehicles equipped with a manual transmission (M/T).



RETAILER RESPONSIBILITY:

Retailers will be advised when parts are available. Once remedy parts are available, retailers are to promptly perform the applicable service procedures to correct all affected vehicles in their inventory (used, demo & SSLP). Additionally, when parts are available, whenever a vehicle subject to this recall is taken into retailer inventory, or in for service, necessary steps should be taken to ensure the recall correction has been made before selling or releasing the vehicle.

If an affected vehicle is in for service before parts become available, please inform the owner that their vehicle is affected by this recall and that remedy parts are not yet available. Subaru is in the process of acquiring the parts necessary to perform this repair, and all affected owners will be notified by mail once remedy parts are available.

Until remedy parts are available, please advise the owner of the information and parking tips listed below, which are also described in the owner's manual. Until this repair can be performed, the driver should do the following when parking the vehicle:

- Whenever possible, park the vehicle in a flat location.
- When parking uphill, the front wheels should be turned away from the curb as shown. Also, be sure to shift the M/T shifter into first gear when parking uphill.
- When parking downhill, the front wheels should be turned into the curb as shown. Also, be sure to shift the M/T shift lever into reverse gear when parking the vehicle downhill.
- Apply the electronic parking brake (EPB) by depressing the brake pedal and pressing the parking brake switch firmly.



Under normal operating conditions, the brake system warning light illuminates with the parking brake applied while the ignition switch is in the "ON" position. The light turns off when the parking brake is released.



However, the brake system warning light flashes when the EPB system is malfunctioning. If the brake system warning light flashes, the driver should park the vehicle in a safe location as soon as possible, taking the above precautions, and contact a Subaru retailer.

If it is confirmed that the EPB system is malfunctioning on an affected vehicle prior to remedy parts being available, please order and install the current replacement part applicable to the vehicle, at no charge to the customer. Please ensure the customer understands that such a replacement would be an interim repair until the modified remedy parts become available.

NOTE: See the Claim Reimbursement and Entry Procedures section for more information regarding interim repair claim submission.

Continued...

OWNER NOTIFICATION:

Subaru will notify affected vehicle owners by first class mail around November 7, 2018, advising them of this recall and that parts are not yet available.

Once parts are available, the affected owners will be notified again by mail, and by email if a valid email address is on file. Parts are expected to be available in the second quarter of 2019.

RETAILER AFFECTED VIN LISTS:

Once parts are available, each Subaru retailer will receive an affected VIN list from their Zone Office when owner re-notification begins. Vehicles will be assigned to retailers in the affected VIN list as follows:

- Original vehicle owners are assigned to the original selling retailer when their current address is within a 100-mile radius of that retailer.
- If the original selling retailer is inactive, the VIN has been assigned to the nearest active retailer.
- For any new owners or when original owners live more than 100 miles from the original selling retailer, the VIN has been assigned to the nearest active retailer.

IMPORTANT: Retailer affected VIN lists include information for vehicles affected by this recall. This information will enable retailers to follow up with owners of affected vehicles. The lists contain owners' names and phone numbers obtained from State Motor Vehicle Registration Records. The use of such motor vehicle registration data for any other purpose is unlawful. Accordingly, retailers are required to limit the use of these lists for the sole purpose of completing this recall.

PART INFORMATION:

Part number information for the replacement EPB actuators applicable to this Product Campaign Bulletin have not been finalized as replacement parts are currently unavailable. This bulletin will be revised with the orderable part numbers when inventory becomes available.

SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

Currently, the existing service procedure for replacing the EPB actuator assembly remain unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time and every time. This includes but is not limited to: important SAFETY precautions, proper inspection criteria, necessary special tools, required processes and related one-time-use parts needed for a complete and lasting repair.

As referenced above, when the EPB actuators applicable to this Product Campaign Bulletin become available, the Service Procedure may need to be revised. If so, this bulletin will be revised with any new information.

Continued...

SERVICE PROGRAM IDENTIFICATION LABEL:

Type or print the necessary information on a Campaign Identification Label. The completed label should be attached to the vehicle's upper radiator support.

Additional labels are available through normal parts ordering channels. The part number is MSA6P1302, which comes as one sheet of 20 labels.

Part Number	Applicability	Description	Order Quantity
MSA6P1302	All Models	Campaign Completion Labels (contains one sheet of 20 labels)	1

SUBARU
Campaign Code
WTV-81
COMPLETED
DIST./DEALER NO.
SERIAL NO.
DO NOT REMOVE

CLAIM REIMBURSEMENT AND ENTRY PROCEDURES:

Credit to perform this recall will be based on properly completed repair order information. Retailers may submit claims through Subarunet.com.

Labor Description	Labor Operation #	Labor Time	Fail Code	Claim Type
WTV-81- EPB Actuator Assembly Replacement	A154-421	1.3	WTV-81	RC

IMPORTANT: When submitting a claim for an interim repair as described in the Retailer Responsibility section above, always use the failure code and labor operation codes from the Labor Time Guide and **NOT** the WTV-81 Service Campaign coding.

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

Continued...

IMPORTANT SAFETY RECALL

This notice applies to the VIN below.



SUBARU

Subaru of America, Inc.
P.O. Box 9103
Camden, NJ 08101-9877
844-373-6614
www.subaru.com

**Subaru Recall WTV-81
NHTSA ID 18V-626
November 2018 – Interim Notice**

Dear Subaru Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

SUBARU OF AMERICA, INC. has decided that a defect, which relates to motor vehicle safety, exists in certain 2010-2014 model year Legacy and Outback vehicles equipped with a manual transmission (M/T). These vehicles are also equipped with an electronic parking brake, which is operated by pushing or pulling the parking brake switch. You received this notice because our records indicate that you currently own one of these vehicles.

REASON FOR THIS RECALL:

Due to improper manufacturing processes, a capacitor on the circuit board and/or the actuator stroke sensor magnetic ring located in the control unit of the electronic parking brake (EPB) may crack over time. If either component develops a crack, the brake system warning lamp will flash, and the EPB may not apply as intended.

If the manual transmission (M/T) shift lever is not in the recommended gear when the vehicle is parked and the EPB does not engage, the vehicle may roll away, increasing the risk of a crash.

Remedy parts are not yet available.



Subaru is in the process of acquiring the parts necessary to perform this repair. Once there is a sufficient supply of parts available, Subaru will contact you again by mail advising you to proceed with scheduling an appointment with your Subaru retailer (dealer). We expect parts to be available in the second quarter of 2019.

Continued...

PRECAUTIONS TO TAKE UNTIL THE REPAIR CAN BE PERFORMED:

Until this repair can be performed, please do the following when parking your vehicle:

- Whenever possible, park your vehicle in a flat location.
- When parking uphill, the front wheels should be turned away from the curb as shown. Also, be sure to shift the M/T shifter into first gear when parking uphill.
- When parking downhill, the front wheels should be turned into the curb as shown. Also, be sure to shift the M/T shift lever into reverse gear when parking your vehicle downhill.
- Apply the electronic parking brake (EPB) by depressing the brake pedal and pressing the parking brake switch firmly



To release the EPB, pull the parking brake switch toward you while the ignition switch is in the "ON" position with both the brake pedal and clutch pedal depressed.

Under normal operating conditions, the brake system warning light illuminates with the parking brake applied while the ignition switch is in the "ON" position. The light turns off when the parking brake is released.



However, the brake system warning light flashes when the EPB system is malfunctioning. If the brake system warning light flashes, park your vehicle in a safe location as soon as possible, taking the above precautions, and contact your Subaru retailer.

WHAT SUBARU WILL DO:

When remedy parts are available, Subaru will replace the electronic parking brake (EPB) actuator in your vehicle at no cost to you. Subaru will notify you again by mail when remedy parts are available, advising you to proceed with scheduling an appointment with your Subaru retailer.

CHANGED YOUR ADDRESS OR SOLD YOUR SUBARU?

If you have moved or sold your vehicle, please complete the enclosed prepaid postcard and mail it to us. Or if you prefer to update this information online, please go to www.subaru.com, select 'Customer Support,' then select 'Address Update' or 'Ownership Update' from the drop-down menu.

IF YOU HAVE PREVIOUSLY PAID FOR A REPAIR:

If you have already paid for repairs associated with this condition, you may be eligible for reimbursement. Reimbursement consideration will be based on the amount an authorized Subaru retailer in your area would charge for the same repair.

Please send the original service repair order, which has the name of the repair facility, date of repair, mileage at the time of repair, complete 17-digit vehicle identification number (VIN), and your name, with correct mailing address and telephone number to the address listed below.

Subaru of America, Inc.

Customer-Retailer Services Department, Attention: WTV-81 Recall

P.O. Box 9103, Camden, NJ 08101-9877

Continued...

Please send original receipts only and retain a photocopy for your records. Please be assured that we will attempt to process your reimbursement request as quickly as possible, but it may take up to 60 days for this process to be completed.

IF YOU NEED FURTHER ASSISTANCE:

To locate the nearest Subaru retailer, you can access our website at www.subaru.com and select 'Find a Retailer.'

For additional information, please go to: <http://www.wtv81.service-campaign.com>.

If you need additional assistance, please contact us directly:

- By e-mail: Go to: www.subaru.com and select "Contact Us."
- By telephone: 1-844-373-6614 Monday through Friday between 8:00 a.m. and 7:00 p.m. ET.
- By U.S. Postal mail: Write us at:

Subaru of America, Inc.
Attn: Customer-Retailer Services Department
P.O. Box 9103, Camden, NJ 08101-9877

To subscribe to the NHTSA Recall Notification E-mail System, please go to:
<https://www-odi.nhtsa.dot.gov/nhtsa/subscriptions>.

Please contact us immediately if the Subaru retailer fails or is unable to make the necessary repairs free of charge.

You may also contact the Administrator, National Highway Traffic Safety Administration (NHTSA), 1200 New Jersey Ave., SE, Washington, DC 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to <http://www.safercar.gov> if you believe the Subaru retailer has failed or is unable to remedy your vehicle without charge within a reasonable amount of time.

Your continued satisfaction with your Subaru is important to us. Please understand that we have taken this action in the interest of your safety and your vehicle's proper operation. We sincerely apologize for any inconvenience this matter may cause and urge you to schedule an appointment as soon as possible.

Sincerely,

Subaru of America, Inc.

Notice to Lessors: Under Federal law the lessor of a vehicle who receives this letter must provide a copy of it to the vehicle lessee(s) within 10 business days from receipt. The lessor must also keep a record of the lessee(s) to whom this letter is sent, the date sent, and the applicable vehicle identification number (VIN). (For the purposes of this section, a lessor means a person or entity that in the last twelve months prior to the date of this notification has been the owner, as referenced on the vehicle's title, of any five or more leased vehicles. A leased vehicle is a vehicle leased to another person for a term of at least four months.)

A subsidiary of SUBARU CORPORATION