trained technicians have the equipment,
do the job correctly and safely. If a cond
Service Bulletin applies to your vehicle,

ATTENTION: IMPORTANT - AII GENERAL MANAGER Service Personnel Should Read and PARTS MANAGER Initial in the boxes CLAIMS PERSONNEL provided, right. SERVICE MANAGER © 2019 Subaru of America. Inc. All rights reserved.

SERVICE INFORMATION BULLETIN

APPLICABILITY:	2014-2019MY Forester 2013-2019 Crosstrek
SUBJECT:	Rear Subframe Bolts: Design Change


INTRODUCTION:

This Service Information Bulletin announces a change made to the rear subframe retaining bolts used on the models listed above. The design changes provide the bolt with an increased durability against rust.

PRODUCTION CHANGE INFORMATION:

The new subframe bolt has been incorporated into production as follows:

Model	Starting VIN
Forester	L*548410
Crosstrek	L*337529



PART INFORMATION:

The part number for the new subframe flange bolt is 20058FL000. The changes made to the bolt (thicker flange and addition of a drainage groove) are shown in the photos below.

REMINDER: Always order the most up-to-date replacement parts based on the specific VIN being repaired. Added Water

> 2mm Thicker Flange

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD **RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.**

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly tools, safety instructions, and know-how to ition is described, DO NOT assume that this or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

Drain Groove

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...



QUALITY DRIVEN® SERVICE

NUMBER: 05-69-19

DATE: 07/23/19

SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

The service procedure for replacing these bolts INCLUDING the torque specification of 145 Nm (107 ft. lbs.) remains unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time and every time.

IMPORTANT NOTES:

- These bolts are **One-Time Use** items.
- These bolts are NOT interchangeable with those used at any other location on the vehicle.
- If rust is identified on the original bolts, replace all 4 bolts with the new type as a set.

Before installing the new bolts, always clean any remaining rust or corrosion from the top, bottom and cross member stoppers along with the subframe support surfaces. CAREFULLY touch-up any exposed bare metal surfaces with a rust-preventative aerosol spray paint.

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.