

- ATTENTION:**
- GENERAL MANAGER
 - PARTS MANAGER
 - CLAIMS PERSONNEL
 - SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

©2018 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2017-**20MY** Impreza
 2018-**20MY** Crosstrek
 2018-19MY Legacy and Outback
 2019-**20MY** WRX and WRX STI
 2019-**20MY** Ascent
 2018-**20MY** BRZ
 2019-**20MY** Forester

NUMBER: 15-226-18R

DATE: 08/21/18

REVISED: 11/15/19

SUBJECT: Harman Audio / Infotainment: Troubleshooting
 USB Functionality Concerns

INTRODUCTION:


This bulletin provides troubleshooting steps to follow when diagnosing customer concerns regarding USB functionality. Please start by completing the Harman Investigation Guide Questionnaire as it gathers important details which will help with diagnosis and will be required should the condition not be resolved by this troubleshooting. While completing the questionnaire, follow the question flow based on the customer concern. Answer each related question noting the results to each in detail while performing the diagnostics. Review the entire bulletin before beginning in order to understand the flow for the listed concern. Please apply the information captured in the checklist to the Harman Investigation Guide Questionnaire. If the concern you have is not listed, check the Service Manual “Infotainment (Diagnostics) - Diagnostics with Phenomena” section as a starting point.

SERVICE PROCEDURE / INFORMATION:

Please complete checklist provided at the end of the document and keep it available for future reference.

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

- 1) Always confirm the condition as reported by the customer.
- 2) This section addresses USB detection symptoms.
 - a. Confirm the USB is recognized (USB icon appears) on the Media screen as shown in the figure to the right.



CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.


Continued...

- b. If the USB is not recognized, follow Service Diagnostic Mode from the Service Manual:
 - i. Turn the ignition switch to ACC.
 - ii. Press the “TUNE/SCROLL” button six times while pressing the “HOME” button.

1. SERVICE INSPECTION:

- a. CONNECTION

- i. On Service Menu, press “**Connection**” to display the list of items.
- ii. **OK**: Each device is connected properly.
- iii. **NG**: Connection is not established, or connection status (possibly including the related harness) is faulty.



NOTES:

- The USB connection showing “NG” when no USB device is connected to USB ports is normal.
- If the concern involves “CarPlay not working”, make sure a genuine Apple cable is used. In some cases, aftermarket cables may cause connection issues.
- If the concern involves “Android Auto not working”, try using another cable since Android phones do not require use of a genuine cable.

- c. Do other USB devices work in the suspect vehicle? If yes, check the USB device’s operation in another like vehicle.
- d. Please provide detailed information regarding the USB device (brand, device type, file system, types of files on device, etc.).


- 3) This section addresses issues related to Apple CarPlay and/or Android Auto not launching consistently due to poor connectivity to USB Media.

New firmware has been released to enhance connectivity for Auxiliary Terminal part numbers used with MID and HIGH level head units.

NOTE: The BASE model utilizes a different Auxilliary Terminal part number which is not affected.

How to determine if the Auxiliary Terminal is pre- or post-countermeasure (CM):

- CAREFULLY peel off the QR code / part number label.
- Check the Lot# as shown below. If the number is after “7411” it is post-CM.



- 4) If the above steps do not resolve the customer’s concern with USB functionality, complete a fresh Harman Investigation Guide Questionnaire documenting the customer’s concern and the results of each diagnostic step in this bulletin. If possible, capture a video of the condition then contact the SOA Techline to review the next steps. Techline will request you send the completed questionnaire, step-by-step bulletin test results and any videos of the condition.

Continued...

**USB FUNCTIONALITY CONCERNS AND TROUBLESHOOTING
CONCERN CHECKLIST**

Repair Order Date: _____

Vehicle Identification Number (VIN): _____

1. Condition confirmed as reported by the customer? **NO:** **YES:**

Concern details: _____

2. Is the cable used to connect the phone OEM? **NO:** **YES:**

3. Head Unit software version: _____

4. Is the USB recognized? **NO:** **YES:**

5. Does the USB connection show “NG”? **NO:** **YES:**

6. Are other USB devices recognized and work properly? **NO:** **YES:**

7. Has USB device been tested using a like vehicle? **NO:** **YES:**

8. USB device details: brand _____, type _____, file system _____, USB hub

9. Part Number: _____ Date Code: _____

Continued...

WARRANTY / CLAIM INFORMATION:

For vehicles within the Basic New Car Limited Warranty period or covered by an active Subaru Added Security Gold plan, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Labor Time	Fail Code	H/U Type
HARMAN USB TROUBLESHOOTING	A850-873	0.5	ZLI-43	Base, Mid & High

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.