



Bulletin No.: PIT5834

Published date: N/A

## Preliminary Information


**PIT5834 A/C Blows Warm Intermittently Or Takes A Long Time To Start Cooling. Vehicles With 11th VIN digit Is S Built Between 09-08-2020 And 09-15-2020**



### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Blazer	2021	September 8, 2020	September 15, 2020	All	All
Chevrolet	Equinox	2021	September 8, 2020	September 15, 2020	All	All

<b>Involved Region or Country:</b>	<b>North America</b>
<b>Condition:</b>	<b>A/C is slow to cool, takes longer to blow cool air when compared to like vehicle.</b>
<b>Cause:</b>	<b>Possible A/C refrigerant contamination.</b>

If you duplicate this condition and there is a noticeable performance difference when compared to another Blazer or Equinox and the vehicle was built during the above time period , recover the refrigerant using the GE-50957 Contaminated Refrigerant Recovery Machine. Remove the line from the condenser and the TXV and look for contamination like illustrated in the pictures below. If you have this contamination, take pictures of the fittings, open a TAC case and attach them to the case. Your case will be reviewed and you will be contacted directly. If you do not see visible contamination like below reinstall the lines and diagnose using the performance chart and diagnostics in Service Information.





### Version History

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>04/14/2021 - Created on.</b>



GENERAL MOTORS

© 2021 General Motors. All Rights Reserved.