

Service Bulletin

21-048

June 30, 2021 Version 2

Driver's Seat Frame Noise

Supersedes 21-048, dated May 28, 2021, to revise the information highlighted in yellow.

AFFECTED VEHICLES

Year	Model	Trim Level	VIN Range		
2018	Accord	EX	1HGCV1JA232738 thru 1HGCV1JA235194		
			1HGCV2JA049936 thru 1HGCV2JA052378		
		Sport	1HGCV1JA236698 thru 1HGCV1JA269156		
			1HGCV2JA048169 thru 1HGCV2JA054592		
		Touring	1HGCV1JA246793 thru 1HGCV1JA246794		
			1HGCV2JA049468 thru 1HGCV2JA054418		
	Accord	EX	1HGCV1KA000304 thru 1HGCV1KA168430		
			1HGCV2KA000639 thru 1HGCV2KA032918		
2019		Sport	1HGCV1KA000909 thru 1HGCV1KA169091		
			1HGCV2KA000298 thru 1HGCV2KA034716		
		Touring	1HGCV2KA000014 thru 1HGCV2KA034770		
2018	Accord Hybrid	EX-L	1HGCV3JA012382 thru 1HGCV3JA015128		
		Touring	1HGCV3JA007089 thru 1HGCV3JA017116		
2019	Accord Hybrid	EX	1HGCV3KA000024 thru 1HGCV3KA020829		
		EX-L	1HGCV3KA000128 thru 1HGCV3KA020984		
		Touring	1HGCV3KA000066 thru 1HGCV3KA020955		

(continued on next page)

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

AFFECTED VEHICLES (CONTINUED)

2018	CR-V	EX	2HKRW1JH519064 thru 2HKRW1JH523679 2HKRW2JH677054 thru 2HKRW2JH699914 5J6RW1JL013496 thru 5J6RW1JL017016 5J6RW2JL028716 thru 5J6RW2JL037692 5J6RW1JA0000274 thru 5J6RW1JA014550 5J6RW2JA000037 thru 5J6RW2JA002730 7FARW1JE049878 thru 7FARW1JE057125 7FARW2JE089576 thru 7FARW2JE106250
		Touring	2HKRW1JH519164 thru 2HKRW1JH521486 2HKRW2JH678837 thru 2HKRW2JH695094 5J6RW1JL013615 thru 5J6RW1JL016540 5J6RW2JL029223 thru 5J6RW2JL037460 7FARW1JE050189 thru 7FARW1JE055383 7FARW2JE089886 thru 7FARW2JE102045
2019	CR-V	EX	2HKRW1KH500094 thru 2HKRW1KH509900 2HKRW2KH600069 thru 2HKRW2KH660211 5J6RW1KL000068 thru 5J6RW1KL007202 5J6RW2KL000237 thru 5J6RW2KL025852 5J6RW1KA000194 thru 5J6RW1KA047193 5J6RW2KA000069 thru 5J6RW2KA018251 7FARW1KE000164 thru 7FARW1KE031755 7FARW2KE000073 thru 7FARW2KE051641
		Touring	2HKRW1KH500003 thru 2HKRW1KH505676 2HKRW2KH600009 thru 2HKRW2KH659701 5J6RW1KL000008 thru 5J6RW1KL004115 5J6RW2KL000001 thru 5J6RW2KL025472 7FARW1KE000183 thru 7FARW1KE018870 7FARW2KE000013 thru 7FARW2KE050711
	Odyssey	LX	5FNRL6KB036508 thru 5FNRL6KB137894
2019		Elito	5FNRL6KB035708 thru 5FNRL6KB138703
		Elite Touring	5FNRL6KB035808 thru 5FNRL6KB126634 5FNRL6KB032754 thru 5FNRL6KB126429
2020	Odyssey	LX	5FNRL6LB000285 thru 5FNRL6LB005445
		EX	5FNRL6LB000586 thru 5FNRL6LB005652
		Elite	5FNRL6LB000011 thru 5FNRL6LB005202
		Touring	5FNRL6LB000047 thru 5FNRL6LB005501
<u>L</u>	I		<u> </u>

REVISION SUMMARY

Under AFFECTED VEHICLES, 2020 Odyssey and 2018 Accord Hybrid VINs were added. VIN ranges were updated throughout the rest of the list.

SYMPTOM

There is a whining, squeak, or squeal type noise coming from the driver's seat frame when adjusting the seat.

POSSIBLE CAUSE

There is insufficient grease applied to the Up-Down Motor nylon gear.

CORRECTIVE ACTION

Apply grease to the Up-Down Motor nylon gear.

REQUIRED MATERIALS

Part Name	Part Number	Quantity
MULTEMP SH-U Grease (1 container repairs 12 vehicles)	08798-9066	1

TOOL INFORMATION

Tool Name	Tool Number	Quantity
Prying Tool	Commercially available	1

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8510B0	2018-19 Accord and 2019 Accord Hybrid Apply grease to the Up-Down Motor nylon gear.	0.3 hr	07409	03214	A21048A	81526-TVA-L11
	2018-19 CR-V Apply grease to the Up-Down Motor nylon gear.				A21048B	81526-TLA-A51
	2019 Odyssey Apply grease to the Up-Down Motor nylon gear.				A21048C	81526-THR-A83

Skill Level: Repair Technician

INSPECTION PROCEDURE

Move the seat to the upmost position. Lower the seat without anyone sitting on it and listen for any whining, squeak or squeal noises. If any noise is heard, move on to repair procedure.

REPAIR PROCEDURE

1. Move the driver's seat to its most forward and highest position.



the way forward.

highest position.

Remove the driver's power seat adjustment cover using the prying tool.



NOTE: Do not disconnect the power seat switch connectors.




DRIVER'S POWER SEAT **SWITCH CONNECTORS** Do not disconnect.

DRIVER'S POWER SEAT ADJUSTMENT COVER

3. Remove the leather cover by detaching it from the bottom.

LEATHER COVER Remove.



4. Using the power seat adjustment switch, move the seat down to the lowest point.

NOTE: This is important to gain access to the nylon gear.


Seat lowered all the way down.



5. Remove the Up-Down Motor nuts.

UP-DOWN MOTOR

UP-DOWN MOTOR NUTS



6. Remove the Up-Down Motor using the prying tool.


NOTE: Before removing the Up-Down Motor, move the seat down to the lowest point.



UP-DOWN MOTOR

PRYING TOOL

NOTE: When removing the Up-Down Motor, the nylon gear may come out with the motor or stay on the seat frame.




NYLON GEAR ON UP-DOWN MOTOR




NYLON GEAR ON SEAT FRAME

7. Remove the nylon gear and apply a layer of grease.

NOTE: Grease must be applied evenly to both metal and nylon teeth.




NYLON GEAR BEFORE GREASE IS APPLIED



NYLON GEAR AFTER GREASE IS APPLIED TO METAL AND NYLON TEETH


8. Install the nylon gear to the seat frame.

NOTE: The metal teeth of the nylon gear must be aligned with the seat frame teeth when reinstalling. The nylon gear should be flush with the frame.



9. Install the Up-Down Motor to the seat frame.

NOTE: Install slowly to make sure the gears fit together.



UP-DOWN MOTOR

10. Torque both nuts to 19 N·m (14 lb-ft).

NOTE: Do not overtighten nuts.



- 11. Operate the seat to confirm proper function, and that the noise is not present.
- 12. Install all removed parts in the reverse order.

END