



# Preliminary Information

## PIT5876 Active Navigation Session Pop up

Proactive

Models

| Brand:    | Model:   | Model Years: | VIN: |     | Engine: | Transmissions: |
|-----------|----------|--------------|------|-----|---------|----------------|
|           |          |              | from | to  |         |                |
| Chevrolet | Suburban | 2022         | All  | All | All     | All            |
| Chevrolet | Tahoe    | 2022         | All  | All | All     | All            |
| GMC       | Hummer   | 2022         | All  | All | All     | All            |
| GMC       | Yukon    | 2022         | All  | All | All     | All            |
| GMC       | Yukon XL | 2022         | All  | All | All     | All            |

|                                   |  |
|-----------------------------------|--|
| <b>Involved Region or Country</b> | <b>United States, Canada, Mexico</b>   |
| <b>Additional Options (RPO)</b>   | IOK  |
| <b>Condition</b>                  | <b>Some customers may comment that, when in an active navigation session using the embedded google maps feature, they will not get a pop-up notification to tell them when to turn if they are not physically on the embedded google maps navigation screen.</b> |
| <b>Cause</b>                      | <b>The cause of this condition is unknown, but the engineering team is aware of the issue and is working on a fix. Please do not replace any parts.</b>  |

**Correction:**

**Until a permanent fix is provided, the temporary solution is to shut the vehicle off to allow it to go to sleep and then cycle the ignition.**

Warranty Information

**For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.**

| Labor Operation | Description                                    | Labor Time |
|-----------------|--|------------|
| 3487528         | Active Navigation session - no pop-up received | 0.2 Hr.    |

**\*This is a unique Labor Operation for Bulletin use only.**

## Customer Information

**Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern. Once a solution is available, this PI will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.**

## Version History

|          |                          |
|----------|--------------------------|
| Version  | <b>1</b>                 |
| Modified | 12/16/2021 - Created on. |



© 2022 General Motors. All Rights Reserved.