

Service Bulletin

Bulletin No.: 21-NA-142

Date: August, 2022

TECHNICAL

Subject: Front Brake Grind/Groan Noise After Sitting Overnight

This bulletin replaces PIT5805B. Please discard PIT5805B.

Brand:	Model:	Model Year:		VIN and DATE Breakpoints:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2020		5GAERBKW8LJ296460			
Cadillac	XT5	2021	2023				
	XT6						
	Blazer	2021				All	All
Chevrolet	Colorado	2021	2022			All	All
	Traverse	2020	2023	1GNERKKW5LJ296020			
GMC	Acadia	2021	2023				
	Canyon	2021	2022				

Involved Region or Country	North America, Russia, Middle East, Palestine, Japan, South Korea, Bolivia, Ecuador, Chile, Colombia, Peru, GM Korea, Uzbekistan.		
Additional Options (RPOs)			
Condition	Some customers may comment on hearing a brake noise on the first few stops. They may describe it as a grind/groan sound, and it may feel like ABS is active, but it is not.		
	The cause of the condition may be the front disc brake pad material.		
Cause	Note: A revised pad material is being developed to address this noise concern and should be available in the November/December timeframe. If the customer is not satisfied with waiting for the new pads, follow the Correction below.		
Correction	 Verify the condition is present and check the pad number stamp on the top edge of the pad. If you see GA9130 or GA9140, and this is the first visit, 1. Replace the front disc brake pads with the parts listed below, refer to Front Disc Brake Pads Replacement in the Service Manual 2. Scuff the rotors. 3. Perform the Brake Pad and Rotor Burnishing procedure. Refer to Brake Pad and Rotor Burnishing in the Service Manual Complete a minimum of 20 stop events. If you see GA9140, and this is a second visit, 1. Replace the front disc brake pads with the parts listed below, refer to Front Disc Brake Pads Replacement in the Service Manual 2. Scuff the rotors. 3. Perform the Brake Pad and Rotor Burnishing procedure. Refer to Brake Pad and Rotor Burnishing in the Service Manual Complete a minimum of 20 stop events. 		

Parts Information

Causal Part	Description	Part Number	Qty
X	Pad Kit-Frt Disc Brk	85520396 (Acadia, Blazer, Enclave, Traverse, XT5 and XT6	1
	Pad Kit-Frt Disc Brk	85139417 (Colorado, Canyon)	

Warranty Information

Repairs made for the specific concern within this bulletin will be covered for a period of 24 months or 24,000 miles or 40,000 km, whichever occurs first.

Labor Operation	Description	Base Labor Time	
2486258*	Front Disc Brake Pads Replacement and Scuff Both Front Rotors	Canyon/Colorado – 1.1 hr Enclave – 1.1 hr Traverse – 1.1 hr Blazer – 1.1 hr Acadia – 1.2 hr XT5 – 1.1 hr XT6 – 1.6 hr	
*This is a unique Labor Operation for Bulletin use only.			

Version	7	
Modified	Released June 21, 2021	
	Revised June 30, 2021 – Replaced LTG Labor Operation with Unique Bulletin Labor Operation	
	Revised July 13, 2021 – Updated Parts Information with New Replacement Service Part # 85520396.	
Revised January 27, 2022 – Updated Breakpoints		
	Revised March 09, 2022 – Changed Blazer End Breakpoint from Date to VIN.	
	Revised April 14, 2022 – Added Note to Cause, Updated Correction, Increased Labor Time and Replaced Labor Operation Number.	
	Revised August 23, 2022 – Added 2023 Model Year to All Models Except Colorado and Canyon.	