



Service Bulletin

Bulletin No.: 22-NA-182


Date: September, 2022

INFORMATION

Subject: Information on 6L80 6L90 8L90 10L80 10L90 10L000 Equipped Vehicles With A Harsh Shift, Shudder, Surge, Stall, Transmission Overheating and/or High Transmission Fluid Temperature

This bulletin replaces PIP5792E. Please discard PIP5792E.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade	2021	2023			All	MHS MHO MQC
Chevrolet	Silverado 1500	2021	2021			All Except L3B	MHS, MHT, MQB MQC MQE MYC
	Silverado 1500 LTD (RPO J21, VIN Digit 5 = W / Y)	2022	2023			All Except L3B	MHS MHT MQB MQC MQE MYC
	Silverado 1500 New (RPO J22, VIN Digit 5 = A / D)	2022				All Except L3B	MHS MHT MQB MQC MQE
	Silverado 2500HD 3500HD	2021				All	MGM MGU MYD
	Suburban	2021				All	MHS MQC
	Tahoe	2021				All	MHS MQC
GMC	Sierra 1500	2021	2021			All Except L3B	MHS MHT MQB MQC MQE MYC
	Sierra 1500 Limited (RPO J21, VIN Digit 5 = 8 / 9)	2022	2023			All Except L3B	MHS MHT MQB MQC MQE MYC
	Sierra 1500 New (RPO J22, VIN Digit 5 = H / U)	2022				All Except L3B	MHS MHT MQB MQC MQE MYC
	Sierra 2500HD 3500HD	2021				All	MGM MGU MYD
	Yukon	2021				All	MHS MQC

Involved Region or Country	North America, Uzbekistan, Middle East, Brazil (Mercosur), Colombia (West), Ecuador (West), Peru (West), Japan, Cadillac Korea (South Korea), Thailand (ASEAN), Europe, Australia, New Zealand.
Condition	<p>Some customers may comment on one or more of the following before or after the transmission has been overhauled:</p> <ul style="list-style-type: none"> • Harsh shifting • Shudder • Surging • Stalling • Transmission overheating <p>Some customers may also comment on above normal transmission fluid temperature.</p>
Cause	This condition may be caused by a twisted cooler line on low mileage vehicles.
	<p>Note: A twisted cooler line may cause DTC P27EC to set in the TCM on ETRS transmissions. (RPO MHS MQC).</p>  <p style="text-align: right;">5758376</p> <p>Inspect for a twisted cooler line, example shown in the graphic above.</p> <p>In some cases, it may be necessary to remove the under body panels in order to clearly see the cooler lines.</p> <ul style="list-style-type: none"> • If the cooler line is twisted, disconnect the cooler line from the transmission auxiliary cooler and untwist it, then reconnect the cooler line. • If the cooler line remains misshaped after untwisting, the cooler line should be replaced then check the transmission fluid level following SI. Add fluid if needed. • If no concerns are found with the rubber line being misshaped, check the transmission fluid level following SI. Add fluid if needed. <p>The Thermal Bypass Valve (TBV) may be the cause of the overheat if a cooler line is not twisted or misshaped. The TBV will open at the following temperatures for the models listed in this TSB. 6 Speed (6L80, 6L90) - 158F (70C) - TBV is external to the transmission 8 Speed (8L90) - 194F (90C) – TBV is external to the transmission 10 Speed (10L80, 10L90, 10L1000) – 143F (61C) – TBV is within the valve body on all listed applications expect those equipped with 3.0 (LM2) Diesel. On the LM2 Diesel the TBV is external to the transmission</p>

Version	1
Modified	Released September 06, 2022

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION