



Service Bulletin

File in Section: -

Bulletin No.: PIT5246B

Date: November, 2014

PRELIMINARY INFORMATION

Subject: Normal Characteristic - Clunk Or Pop Type Noise From Power Lift-Gate Assembly At Full Open Position

Models: 2010 - 2015 Buick Enclave
2010 - 2015 Chevrolet Traverse
2010 - 2015 GMC Acadia

This PI was superseded to update Model Years. Please discard PIT5246A

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may state there is a clunk or pop type noise coming from the power lift-gate assembly when the lift-gate reaches the full open position. They may also notice that the lift-gate drops slightly when this occurs. This noise may be more noticeable when cold outside.

Recommendation/Instructions

If the struts are not weak and can hold the lift-gate open, the struts should NOT be replaced and this noise should be considered a normal condition.

Once the lift gate reaches the full up position, the power lift-gate clutch disengages - leaving the struts to hold the gate in the full up position. It is the clutch disengagement that causes this noise.

Customer Information

Please communicate to the customer this condition is a normal operating characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

ADDITIONAL SI KEYWORDS:

liftgate lift gate

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.