



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-267

Date: August, 2016

INFORMATION

Subject: Unable to Perform Transmission Range Control Module Range Motor Position Learn

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	LaCrosse	2017	2017				
Cadillac	XT5						
Chevrolet	Bolt EV						
Opel	Ampera-e						

Involved Region or Country	North America and N.A. Export Regions
Condition	Some Technicians may comment that they are unable to perform the Transmission Range Control Module (TRCM) Range Motor Position Learn.
Cause	This condition may be caused by the transmission temperature being higher or lower than the range requirement of 50-104°F (10-40°C).

Correction

Note: The TRCM DTCs require the TRCM to be updated and relearned.

The technician or service writer should not idle the engine or drive the vehicle before performing the learn procedure.

Version	1
Modified	

Additional Keywords: C1201, P073D, P073E, P07E4, P07E5, P16F4, P1769, P1771, P1774, P1787, P1789, P174D, P177A, P17AA, P17AB, P17C8, P17CF, P17D5, P173A-P173F, P174B-P174C, P178B-P178E, P17B1-P17B9, P17BA-P17BF, P17AC-P17AE

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION