Technical Bulletin

NISSAN NORTH AMERICA, INC.
Copyright ©

SERVICE BULLETIN

Classification:	Reference:	Date:
EL06-008c	NTB06-065c	September 4, 2007

POWER WINDOW "AUTO UP" INOPERATIVE

**This bulletin amends NTB06-065b. The Applied Vehicles has been expanded.
Please discard all previous versions of this bulletin.**

APPLIED VEHICLES: 2007 – 2008 Versa (C11)
2007 – 2008 Altima Sedan (L32)
2007 – 2008 Altima Hybrid (HL32)
2008 Altima Coupe (CL32)
2004 – 2008 Armada (TA60)
2005 – 2008 Frontier (D40)
2004 – 2008 Maxima (A34)
2003 – 2007 Murano (Z50)
2005 – 2008 Pathfinder (R51)
2004 – 2008 Quest (V42)
2007 – 2008 Sentra (B16)
2004 – 2008 Titan (A60)
2005 – 2008 Xterra (N50)
2003 – 2008 350Z (Z33)
2008 Rogue (S35)

IF YOU CONFIRM

A power window "Auto Up" will not work.

ACTION

Perform the following <u>initialization</u> procedure:

1. Turn the ignition switch ON.

2. Open the window—all the way DOWN.

3. Pull all the way UP on the switch and hold (close the window).

   - Continue holding the switch <u>all the way UP for 4 seconds</u> after the window is closed.

4. Confirm the window is now operating correctly.

   NOTE:
   - If the window is still not operating correctly, refer to ASIST and the Service Manual for further diagnosis and repair information.

   - The above initialization procedure must be performed if any of the following occur:

     ➢ Battery cable is disconnected
     ➢ Power window switch connector is disconnected
     ➢ Power window regulator is replaced
     ➢ Power window motor is replaced
     ➢ Window glass is removed
     ➢ Window glass run rubber is replaced
     ➢ Power window fuse is blown
     ➢ Window is partly opened and/or closed many times without being fully closed.