

General Service Bulletin (GSB):	2009–2012 Escape / Mariner Rear Quarter Panel Wheel Well Corrosion / Perforation Repair Video
GSB Overview:	Refer to this video for an overview of the repair procedure that is provided in the Technical Service Bulletin (TSB) for corrosion / perforation on the quarter panel wheel well
NOTE: This information is not intended to replace or supersede any warranty, parts and service policy, Work Shop Manual (WSM) procedures or technical training or wiring diagram information.	

This video demonstrates the lower level service procedure to repair corrosion / perforation of the quarter panel wheel well on 2009 – 2012 Escape / Mariner vehicles with a patch panel rather than replacing the quarter panel assembly.

Double Click on this [Link](#) to view the video.

