

General Service Bulletin (GSB):	Fiesta Blower Motor – Screen Assembly Replacement Video
GSB Overview:	Refer to this video for an overview of the repair procedure that is provided in the Technical Service Bulletin (TSB) for Fiesta vehicles with lack of heat resulting from a frozen blower motor
NOTE: This information is not intended to replace or supersede any warranty, parts and service policy, Work Shop Manual (WSM) procedures or technical training or wiring diagram information.	

This video demonstrates the removal and replacement procedure for the blower motor screen assembly on Fiesta vehicles. Click on the Link below to view the video.

[http://www.fordservicecontent.com/Ford\\_Content/videos/tsb/Fiesta\\_TSB\\_Final.mp4](http://www.fordservicecontent.com/Ford_Content/videos/tsb/Fiesta_TSB_Final.mp4)

