

<b>Field Action Number</b>	N25-250403
<b>Release notes</b>	<ul style="list-style-type: none"> <li>• Improves Check Engine Light accuracy.</li> <li>• Improves behavior of aero shutter system in freezing temperatures.</li> </ul> <p>During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.</p>
<b>Model Year</b>	2025
<b>Make</b>	GMC Chevrolet
<b>Model</b>	Sierra HD Crew Cab Silverado Crew Cab
<b>Components</b>	ECM (Engine Control Module)