

# 47X/49X Twin Steer Equalizer Beam Bushing Wear

## COMMUNICATION:

FIELD SOLUTION: Fix as Fail

PUBLISH DATE: N/A

## TOPIC BACKGROUND:



### PRIMARY EFFECT:

- 47X/49X twin steer front suspension equalizer bushings are wearing/tearing at low mileages. Symptom reported as audible knocking noise during turning events.
- Equalizer beam bushing used in tandem taperleaf or flat leaf front suspensions.

### AFFECTED MODELS:

- 47X/49X Twin Steer

## VISUALIZATION:



## PROGRESS UPDATES:

- AM pricing finalized with bushing supplier Reyco for correct replacement bushing. Bushing to be made available in AM as service item. Planned 05/30/2026.
- Parts to be then shipped to supplier for further analysis.

## TOPIC RESOLUTION

### PRODUCTION CHANGEOVER WEEK/MONTH:

- N/A
- No change to production at present until root cause is determined

### RESOLUTION:

- LTCA to be determined after root cause has been confirmed
- Depending on root cause analysis, two available options:
  - New design bushing with improved performance
  - Corrective action at beam assembly supplier where the bushing is installed