

L634-
A.12.26

To: After Sales Official Network
Subject: Air vent grid assembly on V8 engine
Date: 04/05/2026
Pages: 3



Campaign code:
L634-A.12.26

Campaign name:
Air vent grid assembly on V8 engine

Model:
Temerario

Model Year:
2026

Markets:
Australia, Canada, Japan, Mexico, Switzerland,
Taiwan, Thailand, United Kingdom, United States,
South Korea

VIN Involved:
From VIN TLA01279 to TLA01496

Important information: before proceeding with the repair, connect to the Warranty Portal and, using the “VIN Info” function, check that:

- the vehicle is actually affected by the instructions contained in this bulletin.

NOTE: some vehicles may not be affected, despite the fact that their Vehicle Identification Number (VIN) falls within the range;

- only replacement parts that correspond to the specific operation, identified by a letter (such as A, B, C, etc.), are to be used for the chassis being repaired.

Example

VIN
17 DIGITS VIN
MODEL NAME
Start Warranty DD/MM/YYYY End Warranty DD/MM/YYYY
Outstanding Campaigns
Code Type Description Bulletin Proc.
LXX-A.XX.XX CAMPAIGN NAME B
Next service planned at date



NOTE:

Operation A will be available only when the instructions require a preliminary check to be performed to determine whether or not the vehicle actually needs updating.

Information for the service network:

During ongoing product monitoring, Automobili Lamborghini S.p.A. requires verification and possible remounting of the PI air vent grille.

Solution for the field:
Air Vent Grille mounting

Spare Parts:

OPERATION B

Part number	Description	Q.ty
07N119207B	Protective Grille	1
N10621601	Screw	2
N01166422	Washer	2

Management of replaced parts:

Store the components that have been removed from the vehicle in an appropriate manner, marking them with their corresponding bar codes so that they can be identified during visits by the competent Area Manager.

Labor time:

Operation A: 0,5 h
Operation B: 0,5 h

Previous bulletins superseded.

None.

Warranty claim instructions:

To request reimbursement for the repair performed, access the “LIASS” system on the Lamborghini portal and, following the

Rev.01

The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A pursuant to copyright law. The company reserves the right to make updates and modifications as needed. The reprinting, reproduction, distribution to unauthorized persons and/or to third parties, and the partial or complete translation of the material contained herein are prohibited without the express written consent of Automobili Lamborghini S.p.A.

Doc. no.: L/V6_M06 Rev.[07]

1/3



instructions in the system's "Manuals" section, generate and fill out a Warranty Request. Select the required campaign and proceed with entry; carefully read the options present in the alert message that displayed by the system (see example) and select the option performed on the vehicle.

Reimbursement will be structured as follows, on the basis of the operation performed:

- **OPERATION A:**
 - o Steps to be executed: 1
 - o Labour time: 0,5 h
- **OPERATION B:**
 - o Steps to be executed: from 1 to 5
 - o Labour time: 0,5 h

Important information:

attach all documents generated during the work carried out, evidence of the work itself, for instance work orders and diagnostic protocols with BETA-Reports.

If one or more of these is missing, it may lead to a rejected reimbursement request.

Fill out the page in the warranty booklet (identified in the image below) in the section "Service and Recall Campaigns":

Tools/Materials required:

Code	Description.	Q.ty
n/a	n/a	n/a



NOTE:

All O.D.I.S. Service technical documentation can be viewed on the app "O.D.I.S. Self Service Guide" available on Lamborghini HUB portal.

**Repair method:****OPERATION A**

Check that the grille 07N119207B is installed. To do so, follow the instructions at the following path.

1. PI electric motor ventilation unit - Installation procedure
Transmission > Transmission > Gearbox > Gearbox Unit > *PI electric motor ventilation unit - Installation procedure*


If the grille is not present, select Operation B and install it using the appropriate fasteners indicated in the Spare Parts table.

OPERATION B:

Follow the instructions given in the Workshop Manual at the following path:

The operation to be performed is the installation of the protective grille, which is not present on the car.

2. PI electric motor ventilation unit - Installation procedure
Transmission > Transmission > Gearbox > Gearbox Unit > *PI electric motor ventilation unit - Installation procedure*

**IMPORTANT:**

The documents which must be provided together with the operation under warranty request are:

- *Produced Repair Order*
- *Saved Diagnostic Protocol with BETA report*

Failure to follow these procedures could lead to the request being rejected.

For more information, please contact your Area Manager or open a ticket to Technical Support in Lamborghini KEY (Request – General Information – After Sales Services - After Sales Technical Support).

Regards,
Lamborghini Service