



Technical Service Bulletin

Technical Service Bulletin: TSB260067

Released Date: 15-May-2026

Accelera™ Diagnostic Tool Software Update Prior to System Control Module

Accelera™ Diagnostic Tool Software Update Prior to System Control Module

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- BES CM0196 EV114B

Issue Summary

Symptom:

- Accelera™ Diagnostics Electronic Service Tool fails to update the System Control Module (SCM) calibration causing the SCM to lock up.

Root Cause:

- Early versions of the Accelera™ Diagnostics Electronic Service Tool have a software issue that can intermittently cause the Accelera™ Diagnostics Tool to fail the SCM calibration update.

Verification

In the Accelera™ Diagnostics Electronic Service Tool verify version V6.5.1340 or later is installed.

Resolution

Download the latest version of the Accelera™ Diagnostics Electronic Service Tool prior to uploading the latest version of the SCM calibration.

Reason for Change

Document History

Date	Details
2026-5-13	Module Created

Last Modified: 15-May-2026