

Reference	SSM76458
Models	Range Rover Velar / L560
Title	L560 Supplemental Restraint System (SRS) DTC's B1408-13, B1409-13, B0020-13, B0028-13
Category	Electrical
Last modified	22-May-2026 18:44:00
Symptom	203000 Basic Electrical

ContentIssue:

Engineering is investigating reports of vehicles diagnosed with the following SRS DTC's

- B1408-13 Driver Seatbelt Anchor Pretensioner Deployment Control - Circuit Open
- B1409-13 Passenger Seatbelt Anchor Pretensioner Deployment Control - Circuit Open
- B0020-13 Left Side Airbag Deployment Control – Circuit Open
- B0028-13 Right Side Airbag Deployment Control – Circuit Open

Cause:

Findings show Driver or Passenger seat harness replacement has been performed to rectify the concern, but no evidence indicating how the harness has faulted is provided in claims.

Action:

In order to investigate the concern further, engineering has requested the following steps be completed if any of the DTC's noted above are diagnosed.

1. Raise an EPQR to report the fault condition and reference this SSM number.
2. Attach clear photos of the seat harness showing any signs of fault or damage.
3. The seat harness must be retained by the retailer's your parts department to allow for processing of a Parts Return Request (PRR).

anBhdhRlcnM7MjAyNi0wNS0yNiQxMjczMzoxNi42OThaQzEwOC4yOS43NS4xMDQ7