

34-101: Peterbilt Model 589 LED Headlamp Integrated Heaters

5/19/2026

 [Edit](#)  [Clone](#)

34-101

Subject

Peterbilt Model 589 LED Headlamp Integrated Heaters

Whats New Abstract

Certain Peterbilt Model 589 chassis equipped with LED headlamps may need a relay and fuses for the integrated heaters to be functional.

Condition

Installing a relay and fuses will make the LED headlamp integrated heaters functional.

Chassis Affected

Vehicle model year 2026 and 2027 Model 589 manufactured between 01/20/2025 and 12/05/2025 equipped with LED headlamps

Action

Fix-as-Fail

If a customer comes into your dealership with nonfunctional LED headlamp integrated heaters, follow the procedure in the Attachments section to install the heater relay and fuses.

Warranty

Starting on **05/19/2026** and through Standard Warranty or any applicable active Extended Warranty, Peterbilt will pay for parts at dealer net plus applicable mark-up and labor:

- **0.1 hours** of labor to install the LED headlamp integrated heater relay and fuses. Select Recommended Repair Code **34-101**.
- File an additional claim for extraordinary circumstances. A recommended repair for standard labor must be filed first.

- File the claim within 14 days in accordance with the Warranty Policy.

Take-Off Parts Disposition:

- N/A

PRWS CLAIM CODING			
Campaign Code:	34-101	Campaign Type:	Field Repair
Claim Category:	Truck	Repair Type:	Fix-As-Fail
Customer Concern Code:	022	Causal Code:	46
Corrective Action Code:	17	Responsibility Code:	CAMP
Failure Location:	034-001-001	Causal Part:	CB12755
Supplier:	N/A	SRT Code:	B26-25A 0.1 hours Bulletin 34-101: Model 589 LED Headlamp Integrated Heaters

Parts

Quantity	Part Number	Description
2	M1N20	FUSE-20 AMP
1	CB12755	RELAY-SPST ISO 70AMP NO, SEALED
1	Source Locally	PEN WITH PERMANENT INK

Procedure

**WARNING!**

Repair or maintenance procedures may pose a safety risk in limited circumstances. You must read all procedure steps before performing any work and follow all dealership safety procedures or precautions. Failure to comply may result in death, personal injury, equipment damage, or property damage.

Please see the Attachments section below for procedures on installing the LED headlamp integrated heater relay and fuses.

Attachments

[34-101: Peterbilt Model 589 LED Headlamp Integrated Heaters - Repair Procedure](#)