

## TRIUMPH DIAGNOSTIC TOOL 2026-05.2: TRACKER 400 & THRUXTON 400 UNLOCKING

An issue has been identified with some Tracker 400 and Thruxton 400 models that may cause the ABS to report as Not Connected in Smart Scan, preventing PDI unlocking.

A fix for this has been implemented in TDT version **2026-05.2** which is now available to download and update your workshop PC. TDT version 2026-05.2 is only required to resolve the above concern, otherwise TDT 2026-05.1 can continue to be used.

- Please ensure your workshops and relevant staff are aware of the contents.
- Please also update your workshop service manuals, procedures, and have a printed copy available where appropriate.
- **PLEASE ENSURE ABSENT STAFF ARE INFORMED ON THEIR RETURN.  
(Remember to update those returning from holidays/absence)**

The release notes are stored and available to download at any time from the dedicated TDT page within TOL.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.