



Service Bulletin

Bulletin No.: PIP6120

Date: June, 2026

PRELIMINARY INFORMATION

Subject: Possible Stall Or Stumble When Coming Out Of Auto Stop

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2026		All	All	1.3 L3T	CVT
Chevrolet	Trailblazer	2026		All	All	1.3 L3T	CVT

Involved Region or Country	North America
Condition	Potential engine stall or stumbling when coming out of auto stop event
Cause	GM Engineering currently investigating this issue.

Correction

No repairs should be attempted at this time, as GM Engineering is actively investigating the issue and the PI will be updated or replaced with TSB once a determination has been made.

As a temporary workaround, please advise the customer to deactivate the Auto Stop feature during each ignition cycle to help avoid this condition.

Version	1
Modified	06/03/2026 - Created on

