

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title Difficulty Closing and Opening the Glovebox		Ref. No. TJ 37355.2.0	
Issuer (Dept.) Technical Service		Issue Date 4/28/26	Status Date 5/5/26
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 8810	
Function Description Instrument and radio panel		Page Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

If you are unable to open or close the glovebox compartment, follow advice under Service.

CSC Customer Symptom Codes

Code	Description
N3	Instrument panel/dashboard/Gaps, fits poorly, difficult to open or close/Glove box lid
47	Central locking/Glovebox locking/unlocking does not work
WM	Center console/Lid difficult to open/close or broken

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
356							2025-2025		-	202417-202515

SERVICE:

A replacement of the glovebox motor is recommended as a fix. Please follow the method in VIDA (VST OP-number: 88282-2) to replace the motor.

Note: If you face difficulty in opening the glovebox, follow the method in VIDA, VCC-522725-2 "Emergency opening of glove box".

***Failing Part:** 32285654

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ. Note that the TJ number must be stated in the repair order text.

Technical Journal 37355.2.0

VST Operation Number

VST Operation Number	Description
88282-2	Door Latch, glove compartment

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8810.