



Service Bulletin

Bulletin No.: PIP6116

Date: June, 2026

PRELIMINARY INFORMATION

Subject: 1.2L LIH / LPB Turbocharger 25207819 TAC Part Restriction

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2024-2026		All	All	1.2 LBP / LIH	All
Buick	Envista	2024-2026		All	All	1.2 LBP / LIH	All
Chevrolet	Trailblazer	2024-2026		All	All	1.2 LBP / LIH	All
Chevrolet	Trax	2024-2026		All	All	1.2 LBP / LIH	All

Involved Region or Country	North America
Condition	As part of our ongoing quality improvement efforts and to ensure 1.2 LBP/LIH turbocharger replacement is necessary, the turbocharger part number 25207819 has been placed on a part restriction through TAC.
Cause	This restriction is intended to assist dealers with determining if the turbocharger needs to be replaced.

Correction

Follow SI (Service Information) diagnostics prior to contacting GM Technical Assistance for part authorization.

- Link to #25-NA-227: P0299 Low Fuel Concern (Doc ID 6991511)
- Link to DTC P0234 or P0299 (Doc ID 6289641)

U.S. Dealers:

Please contact GM Technical assistance (TAC) by initiating TAC CXC (CX Connect) Case in Global Connect.

Cause This restriction is intended to assist dealers with determining if the turbocharger needs to be replaced.

Canadian Dealers:

Call 1-800-263-7740 for English or 1-800-263-7960 for French.

Parts Information

Description	Part Number	Qty
Turbocharger	25207819	1

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
Use Published Labor Operation For Application	Turbocharger Replacement	Use Published Labor Time For Application

Version	1
Modified	06/03/2026- Created on.

