

46-027: Pre-Production PACCAR EPowertrain De-Energizing Procedures

6/12/2026

 [Edit](#)  [Clone](#)

46-027

Subject

Pre-Production PACCAR EPowertrain De-Energizing Procedures

Whats New Abstract

The currently published HD BEV Chassis with PACCAR EPowertrain Service (Built After 1/14/2026) de-energizing Procedures on ServiceNet cannot be utilized for certain pre-production Battery Electric Vehicle (BEV) chassis.

Condition

Certain pre-production BEV chassis lack a P088 service disconnect. The current PACCAR EPowertrain De-energizing Procedures in the SM046-002 - HD BEV Chassis with PACCAR EPowertrain Service (Built After 1/14/2026) manual on ServiceNet apply only to production-level chassis with the P088 service

disconnect. A new manual has been released for energizing and de-energizing these pre-production chassis.

Chassis Affected

All pre-production BEV chassis built without a P088 service disconnect

Action

Informational

For repairs involving energizing and de-energizing chassis **without** the P088 service disconnect, refer to service manual **SM046-009 - HD BEV Chassis with PACCAR EPowertrain De-energizing and Re-energizing Procedure (Built Before 1/15/2026)** service manual in ServiceNet.

Pre-production chassis **without** the P088 service disconnect include a note in the Truck Notes section of the Service Information Record (SIR) directing dealers to this bulletin and procedure. These chassis are also listed in the attached chassis list.

Warranty

This bulletin is informational only and is not a proactive campaign. Do not reference this bulletin number in the campaign code section when filing claims.

Procedure



WARNING!

Repair or maintenance procedures may pose a safety risk in limited circumstances. You must read all procedure steps before performing any work and follow all dealership safety procedures or precautions. Failure to comply may result in death, personal injury, equipment damage, or property damage.

For repairs involving energizing and de-energizing chassis **without** the P088 service disconnect, refer to service manual **SM046-009 - HD BEV Chassis with PACCAR EPowertrain De-energizing and Re-energizing Procedure (Built Before 1/15/2026)** service manual in ServiceNet.

Attachments

[SM046-009 - HD BEV Chassis with PACCAR EPowertrain De-energizing and Re-energizing Procedure \(Built Before 1/15/2026\)](#)

[46-027 - KW Chassis List - Chassis Without the P088 Service Disconnect](#)

46-027: Pre-Production PACCAR EPowertrain De-Energizing Procedures

6/12/2026

 [Edit](#)  [Clone](#)

46-027

Subject

Pre-Production PACCAR EPowertrain De-Energizing Procedures

Whats New Abstract

The currently published HD BEV Chassis with PACCAR EPowertrain Service (Built After 1/14/2026) de-energizing Procedures on ServiceNet cannot be utilized for certain pre-production Battery Electric Vehicle (BEV) chassis.

Condition

Certain pre-production BEV chassis lack a P088 service disconnect. The current PACCAR EPowertrain De-energizing Procedures in the SM046-002 - HD BEV Chassis with PACCAR EPowertrain Service (Built After 1/14/2026) manual on ServiceNet apply only to production-level chassis with the P088 service

disconnect. A new manual has been released for energizing and de-energizing these pre-production chassis.

Chassis Affected

All pre-production BEV chassis built without a P088 service disconnect

Action

Informational

For repairs involving energizing and de-energizing chassis **without** the P088 service disconnect, refer to service manual **SM046-009 - HD BEV Chassis with PACCAR EPowertrain De-energizing and Re-energizing Procedure (Built Before 1/15/2026)** service manual in ServiceNet.

Pre-production chassis **without** the P088 service disconnect include a note in the Truck Notes section of the Service Information Record (SIR) directing dealers to this bulletin and procedure. These chassis are also listed in the attached chassis list.

Warranty

This bulletin is informational only and is not a proactive campaign. Do not reference this bulletin number in the campaign code section when filing claims.

Procedure



WARNING!

Repair or maintenance procedures may pose a safety risk in limited circumstances. You must read all procedure steps before performing any work and follow all dealership safety procedures or precautions. Failure to comply may result in death, personal injury, equipment damage, or property damage.

For repairs involving energizing and de-energizing chassis **without** the P088 service disconnect, refer to service manual **SM046-009 - HD BEV Chassis with PACCAR EPowertrain De-energizing and Re-energizing Procedure (Built Before 1/15/2026)** service manual in ServiceNet.

Attachments

[SM046-009 - HD BEV Chassis with PACCAR EPowertrain De-energizing and Re-energizing Procedure \(Built Before 1/15/2026\)](#)

[46-027 - PB Chassis List - Chassis Without the P088 Service Disconnect](#)