

45-072: Cummins Modified Troubleshooting for Fault Code 8156

 [Edit](#)  [Clone](#)

Number

45-072

Subject

Cummins Modified Troubleshooting for Fault Code 8156

Supplier

Cummins

Date

6/12/2026

Condition

Active fault code 8156 indicates a communication error between the Cummins Acumen Connectivity Module and the Engine Control Module (ECM).

Chassis Affected

All Ethernet Multiplexed Architecture (EMUX) chassis with a Cummins engine built before 12/21/2025 and with active fault code 8156

Action

Informational

Dealers should be aware that Cummins has published TSB220086: Modified Troubleshooting for Fault Code 8156 to supplement troubleshooting for fault code 8156, which indicates that the ECM did not receive an expected message from the Cummins Acumen Connectivity Module. Cummins QuickServe will direct technicians to TSB220086 as needed during troubleshooting.

Refer to Cummins TSB220086 in the Links section or, for the latest version, in Cummins QuickServe.

Links

[Cummins TSB220086: Modified Troubleshooting for Fault Code 8156](#)

45-072: Cummins Modified Troubleshooting for Fault Code 8156

 [Edit](#)  [Clone](#)

Number

45-072

Subject

Cummins Modified Troubleshooting for Fault Code 8156

Supplier

Cummins

Date

6/12/2026

Condition

Active fault code 8156 indicates a communication error between the Cummins Acumen Connectivity Module and the Engine Control Module (ECM).

Chassis Affected

All Ethernet Multiplexed Architecture (EMUX) chassis with a Cummins engine built before 12/21/2025 and with active fault code 8156

Action

Informational

Dealers should be aware that Cummins has published TSB220086: Modified Troubleshooting for Fault Code 8156 to supplement troubleshooting for fault code 8156, which indicates that the ECM did not receive an expected message from the Cummins Acumen Connectivity Module. Cummins QuickServe will direct technicians to TSB220086 as needed during troubleshooting.

Refer to Cummins TSB220086 in the Links section or, for the latest version, in Cummins QuickServe.

Links

[Cummins TSB220086: Modified Troubleshooting for Fault Code 8156](#)