

REFERENCE:	TSB: 23-007-26 REV. A GROUP: 23 - Body	Date:	June 13, 2026	REVISION:	23-007-26
VEHICLES AFFECTED:	2019 - 2022 (DT) RAM 1500 Pickup This bulletin applies to vehicles built on or after August 01, 2018 (MDH 0801XX) and on or before July 25, 2022 (MDH 0725XX).			MARKET APPLICABILITY: ☒ NA☐ CH ☐ EE☐ IAP ☐ SA☐ MEA NOTE: This bulletin applies to the North American markets.	
CUSTOMER SYMPTOM:	Customers may comment on the following: Wrinkles or bubbles in the instrument panel cover Fig. 1.				
CAUSE:	Manufacturing defect				

This bulletin supersedes Technical Service Bulletin (TSB) 23-007-26, date of issue March 12, 2026, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include an updated Spare Parts table.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-048 date of issue March 12, 2026.



Fig. 1
Wrinkles Or Bubbles In The instrument Panel Cover

REPAIR SUMMARY:

This bulletin involves inspecting and possibly replacing the instrument panel cover.

NOTE: Only vehicles still under the basic warranty are covered in this TSB.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-11-14-9N	Cover, Instrument Panel – Replace (1 - Semi-Skilled)	6 - Electrical and Body Systems	2.3 Hrs.
23-11-14-62	Center Console Equipped (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.3 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	6PB071C1AG	Base Panel	Indigo/Frost
1 (AR)	CXLLXA81AA	Base Panel	Mountain Brown
1 (AR)	6PB061XTAH	Base Panel	Black/New Saddle
1 (AR)	6PB071X9AH	Base Panel	Black
1	06505656AA	Screw, Hex Flange Head, M10 x 1.5 x 35	Single Use Steering Wheel Bolt

DIAGNOSIS:

If the customer describes any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: This is not a proactive repair. This Repair Procedure is to only be performed under this RSU if the vehicle exhibits the symptom/conditions listed in this document and are still under the basic warranty.

1. Replace the instrument panel cover. Refer to the detailed procedures available in DealerCONNECT > Service Library> under: 23 - Body / Instrument Panel / Cover, Instrument Panel / Removal and Installation.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.