

## GPOP - Issue Review System

**Part Number:** 68341437A\$

**Part Description:** Auxiliary Lighting Module

**Issue Description:** Ambient cabin light fault B2811-02 inop. If Ambient Lights can change color and intensity, do not replace Auxiliary/Ambient Lighting Module (ALM). Follow the diagnostic for B2811-02. Before replacing, verify the vehicle PROXI is correct for the vehicle (2-row/3-row). If PROXI is incorrect, re-PROXI and then perform a hard reset of the ALM.