

WORK DESCRIPTION FOR FIELD MEASURE

Code: 26P8891012

Version: 2.0

Check vehicle for dummy bumper; replace if fitted, and renew longitudinal member panel

Model 192

Work Procedure

1. Check the front and rear bumper component parts for any quality defects. The component parts may also exhibit visible irregularities such as incorrect installation, wrong parts fitted, missing parts, holes or paint defects



Illustration 1 (Example of front bumper) *Dummy stickers should be removed



Illustration 2 (Example of rear bumper) *Dummy stickers should be removed

- A. Dummy bumper fitted to vehicle: Perform work procedure A and B.

Work procedure A

1. Replace longitudinal member panel at right and left.

i Does not apply to VIN W1KRJ4xxxxxx11347!

i Please send an email to your AOM with the subject “Code 26P8891012” and include the following information!

- Vehicle identification number (VIN)
- Address of ordering dealer to which the component part is to be sent

Work procedure B

1. Replace the dummy bumpers fitted to the vehicle.

i Please send an email to your AOM with the subject “Code 26P8891012” to have parts ordered!

- Vehicle identification number (VIN)
- Which component part is affected? (front bumper, rear bumper)
- Provide documentation of the dummy component parts, including a representative photo of each part
- Address of ordering dealer to which the component part is to be sent

i The new replacement parts (body parts) will undergo an internal check before being sent free of charge to the specified address.

i Scrap the dummy component parts!

Parts

i Parts will be ordered by contacting your AOM with above information provided.

i Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list, but may be claimed as needed. The required small parts are taken into account in the budgeting.

Operation text and target time

Operation no.	Operation text	Target time	Accounting no./ damage code
11-0126	Check vehicle for dummy component parts Includes: Send documentation to pool address per email	0.2	88 910 12
11-0127	Replace front bumper (after check)	ZM	88 910 12
11-0128	Replace rear bumper (after check)	ZM	88 910 12
11-0129	Replace left and right longitudinal member panel	ZM	88 910 12

*The prescribed times are available in the relevant systems, e.g. XENTRY Operation Time (XOT).