

CE030 MX Component Specific Emissions Warranty for EMY2021 PACCAR MX-11 and MX-13 Engines

6/24/2026

 [Edit](#)  [Clone](#)

MX Component Specific Emissions Warranty for EMY2021 PACCAR MX-11 and MX-13 Engines

Whats New Abstract

6/24/2026-14 fuel injector part numbers (seven for MX-11 and seven for MX-13 engines) have been added to this warranty policy.

Introduction

U.S. & Canada Federal emissions regulates that the warranty coverage is a period of ten (10) years or 435,000 miles (700,000 km), 22,000 engine hours, whichever comes first, from the original warranty registration date, for these specific components on the EMY2021 PACCAR MX-11 and MX-13 Engines. PACCAR has implemented the extension and it is effective retroactively, unless the part is listed as ineligible for reimbursement below.

Revision

06/24/2026 – 14 fuel injector part numbers (seven for MX-11 and seven for MX-13 engines) have been added to this warranty policy.

3/24/2025 – New injector part numbers added to MX component specific emissions warranty

Condition

Units that have coverage under this warranty will be identified in the Service Information Record (SIR):

| Sales Code | Coverage Description |
|------------|--------------------------------------------------------------------|
| 9202161 | EW: MX Emissions 10yr/435K Miles (700K KM) – See CE030 for Details |

Submit a long-form warranty claim through PRWS, using the applicable claim type shown in the chart below, for any repair that meets the requirements of this bulletin. If the repair falls under campaign E290,

| | | | |
|--------------|-----------------------------|--------|-------------|
| 2460409(PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-004-001 |
| 2460410(PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-004-001 |
| 2460411(PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-004-001 |
| 2460412(PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-004-001 |
| 2460413(PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-004-001 |
| 2460414(PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-004-001 |
| 2434417(PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-004-001 |
| 2434418(PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-004-001 |
| 2461235(PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-004-001 |
| 2461236(PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-004-001 |
| 2477784(PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-004-001 |
| 2477785(PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-004-001 |
| 2477786(PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-004-001 |
| 2477787(PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-004-001 |
| 2477862(PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-004-001 |
| 2477863(PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-004-001 |
| 2477864(PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-004-001 |
| 2477865(PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-004-001 |
| 2491046(PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-004-001 |
| 2491047(PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-004-001 |

For reimbursement of past repairs, unless noted above as not eligible, file a claim, and populate parts and labor costs as a sublet in the Miscellaneous section. Attach an invoice and receipt to the claim to document the repair and payment made. In addition, attach a receipt of reimbursement made to the customer for the initial invoice/costs of repair. Retroactive claims without these items will be denied.

Warranty

The emissions warranty will cover the repair costs for any failure of an emission-related part described in this bulletin that results under normal use and service, caused by a warrantable failure, which must be the

result of a defect in material and/or factory workmanship. Reimbursement will include:

- Parts
- Labor
- Consumables (when not reusable)

Please submit a claim using the following claim types:

PROACTIVE REPAIRS ARE NOT COVERED BY THIS PROGRAM.

Towing will only be covered if engine emission component failure occurs within the base engine period of 24 months/250,000 miles/6,250 hours. Outside of base engine coverage, towing, and travel are

excluded. PACCAR will pay for reasonable labor costs for engine removal and reinstallation when necessary to repair a warrantable failure.

The emissions warranty is retroactive and applies to qualifying warrantable failures that customers have

| | | |
|------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|--|
| | 2477786 (PEX) ⁽²⁾ 2477862 (PEX) ⁽²⁾ 2477864 (PEX) ⁽²⁾ 2491046 (PEX) ⁽²⁾ | |
| ⁽¹⁾ Part added in a previous update. ⁽²⁾ Part added in latest update. | | |

Procedure

[CE030: MX Component Specific Emissions Extended Warranty for EMY2021 PACCAR MX-11 and MX-13 Engines US Customer Letter](#)

[CE030: MX Component Specific Emissions Extended Warranty for EMY2021 PACCAR MX-11 and MX-13 Engines US Customer Letter – Spanish](#)

[CE030: MX Component Specific Emissions Extended Warranty for EMY2021 PACCAR MX-11 and MX-13 Engines CAN Customer Letter](#)

[CE030: MX Component Specific Emissions Extended Warranty for EMY2021 PACCAR MX-11 and MX-13 Engines CAN Customer Letter – French](#)

[CE030: MX Component Specific Emissions Extended Warranty for EMY2021 PACCAR MX-11 and MX-13 Engines Chassis List](#)



Kenworth Truck Company
 Customer Service Department
 C/O PACCAR Parts
 750 Houser Way North
 Renton, WA 98057
 (425) 828-5888

[Date]

Subject: CE030: MX Component Specific Emissions Extended Warranty for
 EMY2021 PACCAR MX-11 and MX-13 Engines

Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Kenworth Customer,

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless you experience a problem with your vehicle.

This letter has been sent to inform you that Kenworth Truck Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. **No action is needed on your part.**

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty Coverage (EWC Code 9202161)

| Part Name | Part Number | Result of Failure |
|------------------------------|------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| Fuel Injector (MX-13, EPA21) | 2314737 (PEX) ⁽¹⁾ | Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning. |
| | 2383579 (PEX) ⁽¹⁾ | |
| | 2394548 (PEX) ⁽¹⁾ | |
| | 2403201 (PEX) ⁽¹⁾ | |
| | 2403776 (PEX) ⁽¹⁾ | |
| | 2403778 (PEX) ⁽¹⁾ | |
| | 2423652 (PEX) ⁽¹⁾ | |
| | 2423654 (PEX) ⁽¹⁾ | |
| | 2426854 (PEX) ⁽¹⁾ | |
| | 2426856 (PEX) ⁽¹⁾ | |
| | 2428774 (PEX) ⁽¹⁾ | |
| | 2429855 (PEX) ⁽¹⁾ | |
| | 2452062 (PEX) ⁽¹⁾ | |
| | 2460410 (PEX) ⁽¹⁾ | |
| | 2460412 (PEX) ⁽¹⁾ | |
| | 2460414 (PEX) ⁽¹⁾ | |
| | 2434417 (PEX) ⁽²⁾ | |
| 2461236 (PEX) ⁽²⁾ | | |
| 2477785 (PEX) ⁽²⁾ | | |
| 2477787 (PEX) ⁽²⁾ | | |



A **PACCAR** COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

| | | |
|------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| | 2477863 (PEX) ⁽²⁾ 2477865 (PEX) ⁽²⁾ 2491047 (PEX) ⁽²⁾ | |
| Fuel Injector (MX-11, EPA21) | 2314736 (PEX) ⁽¹⁾ 2383578 (PEX) ⁽¹⁾ 2394547 (PEX) ⁽¹⁾ 2403200 (PEX) ⁽¹⁾ 2403775 (PEX) ⁽¹⁾ 2403777 (PEX) ⁽¹⁾ 2423651 (PEX) ⁽¹⁾ 2423653 (PEX) ⁽¹⁾ 2426853 (PEX) ⁽¹⁾ 2426855 (PEX) ⁽¹⁾ 2428773 (PEX) ⁽¹⁾ 2429854 (PEX) ⁽¹⁾ 2452061 (PEX) ⁽¹⁾ 2460409 (PEX) ⁽¹⁾ 2460411 (PEX) ⁽¹⁾ 2460413 (PEX) ⁽¹⁾ 2434418 (PEX) ⁽²⁾ 2461235 (PEX) ⁽²⁾ 2477784 (PEX) ⁽²⁾ 2477786 (PEX) ⁽²⁾ 2477862 (PEX) ⁽²⁾ 2477864 (PEX) ⁽²⁾ 2491046 (PEX) ⁽²⁾ | Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning. |
| ⁽¹⁾ Components that were included in a previous letter. ⁽²⁾ Additional component added to Extended Warranty Coverage. | | |

If you have previously paid to replace one of the components listed in the tables above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Kenworth Dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest dealer please scan the QR code at the top of this letter or use the Dealer Locator at www.Kenworth.com. When contacting your selected Kenworth dealer, refer to Extended Warranty Code (EWC) **9202161** and the VIN listed on this letter.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.



A **PACCAR** COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

Sincerely,

Kenworth Customer Service



Kenworth Truck Company
 Customer Service Department
 C/O PACCAR Parts
 750 Houser Way North
 Renton, WA 98057
 (425) 828-5888

[Date]

Subject: CE030: MX Component Specific Emissions Extended Warranty for
 EMY2021 PACCAR MX-11 and MX-13 Engines

Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Kenworth Customer,

This notice is sent to you in accordance with the requirements of the Canadian Environmental Protection Act, 1999.

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless you experience a problem with your vehicle.

This letter has been sent to inform you that Kenworth Truck Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. No action is needed on your part.

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty Coverage (EWC Code 9202161)

| Part Name | Part Number | Result of Failure |
|------------------------------|------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| Fuel Injector (MX-13, EPA21) | 2314737 (PEX) ⁽¹⁾ | Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning. |
| | 2383579 (PEX) ⁽¹⁾ | |
| | 2394548 (PEX) ⁽¹⁾ | |
| | 2403201 (PEX) ⁽¹⁾ | |
| | 2403776 (PEX) ⁽¹⁾ | |
| | 2403778 (PEX) ⁽¹⁾ | |
| | 2423652 (PEX) ⁽¹⁾ | |
| | 2423654 (PEX) ⁽¹⁾ | |
| | 2426854 (PEX) ⁽¹⁾ | |
| | 2426856 (PEX) ⁽¹⁾ | |
| | 2428774 (PEX) ⁽¹⁾ | |
| | 2429855 (PEX) ⁽¹⁾ | |
| | 2452062 (PEX) ⁽¹⁾ | |
| | 2460410 (PEX) ⁽¹⁾ | |
| | 2460412 (PEX) ⁽¹⁾ | |
| | 2460414 (PEX) ⁽¹⁾ | |
| 2434417 (PEX) ⁽²⁾ | | |
| 2461236 (PEX) ⁽²⁾ | | |



A PACCAR COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

| | | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| | 2477785 (PEX) ⁽²⁾ 2477787 (PEX) ⁽²⁾ 2477863 (PEX) ⁽²⁾ 2477865 (PEX) ⁽²⁾ 2491047 (PEX) ⁽²⁾ | |
| Fuel Injector (MX-11, EPA21) | 2314736 (PEX) ⁽¹⁾ 2383578 (PEX) ⁽¹⁾ 2394547 (PEX) ⁽¹⁾ 2403200 (PEX) ⁽¹⁾ 2403775 (PEX) ⁽¹⁾ 2403777 (PEX) ⁽¹⁾ 2423651 (PEX) ⁽¹⁾ 2423653 (PEX) ⁽¹⁾ 2426853 (PEX) ⁽¹⁾ 2426855 (PEX) ⁽¹⁾ 2428773 (PEX) ⁽¹⁾ 2429854 (PEX) ⁽¹⁾ 2452061 (PEX) ⁽¹⁾ 2460409 (PEX) ⁽¹⁾ 2460411 (PEX) ⁽¹⁾ 2460413 (PEX) ⁽¹⁾ 2434418 (PEX) ⁽²⁾ 2461235 (PEX) ⁽²⁾ 2477784 (PEX) ⁽²⁾ 2477786 (PEX) ⁽²⁾ 2477862 (PEX) ⁽²⁾ 2477864 (PEX) ⁽²⁾ 2491046 (PEX) ⁽²⁾ | Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning. |
| <p>⁽¹⁾ Components that were included in a previous letter.</p> <p>⁽²⁾ Additional component added to Extended Warranty Coverage.</p> | | |

If you have previously paid to replace one of the components listed in the tables above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Kenworth Dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest dealer please scan the QR code at the top of this letter or use the Dealer Locator at www.Kenworth.com. When contacting your selected Kenworth dealer, refer to Extended Warranty Code (EWC) **9202161** and the VIN listed on this letter.



A **PACCAR** COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.

Sincerely,

Kenworth Customer Service

CE030 - MX Component Specific Emissions Warranty for EMY2021 PACCAR MX Engines

6/19/2026

 [Edit](#)  [Clone](#)

Whats New Abstract

14 fuel injector part numbers (seven for MX-11 and seven for MX-13 engines) have been added to this warranty policy.

Introduction

U.S. & Canada Federal emissions regulates that the warranty coverage is a period of ten (10) years or 435,000 miles (700,000 km) or 22,000 engine hours from the original warranty registration date, whichever comes first, for these specific components on the MY2021 PACCAR MX-11 and MX-13 Engines. PACCAR has implemented the extension and it is effective retroactively unless the part is listed as ineligible for reimbursement below.

Revision

06/19/2026 – 14 fuel injector part numbers (seven for MX-11 and seven for MX-13 engines) have been added to this warranty policy.

03/26/2025 – Fuel injector part numbers for MX-11 and MX-13 engines have been added to this warranty policy.

Condition

Units that have coverage under this warranty will be identified in Service Information Record (SIR):

| Sales Code | Coverage Description |
|------------|--------------------------------------------|
| 9480835 | EW: MX Emissions 10yr/435K Miles (700K KM) |

If there is a failure on any of the parts listed above, submit a warranty claim through PACCAR Registration and Warranty System (PRWS). Ensure the correct VIN number and Causal Part removed from the vehicle are on the submitted claim.

Emissions claims without a causal part will be Resolved-Denied or returned in Denied-Open

Appeal status for correction.

Please use the following coding when submitting your warranty claim:

| PPD Part Number | Part Description | Claim Type | Failure Location |
|------------------------|-----------------------------|-------------------|-------------------------|
| 2314736 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2314737 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-004-001 |
| 2383578 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2383579 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2394547 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2394548 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2403775 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2403776 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2403200 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2403201 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2403777 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2403778 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2423651 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2423652 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2423653 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2423654 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2426853 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2426854 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2426855 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2426856 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2429854 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2429855 (PEX) | Fuel Injector, MX-13, | Engine | 044-014-001 |

| | EPA21 | | |
|---------------|--------------------------------|--------|-------------|
| 2428773 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2428774 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2452061 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2452062 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2460409 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2460410 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2460411 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2460412 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2460413 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2460414 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2434417 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2434418 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2461235 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2461236 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2477784 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2477785 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2477786 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2477787 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2477862 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2477863 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2477864 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2477865 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |
| 2491046 (PEX) | Fuel Injector, MX-11, EPA21 | Engine | 044-014-001 |
| 2491047 (PEX) | Fuel Injector, MX-13, EPA21 | Engine | 044-014-001 |

For reimbursement of past repairs, unless noted above as not eligible, file a claim, and populate parts and labor costs as a sublet in the Miscellaneous section. Attach an invoice and receipt to the claim to document the repair and payment made. In addition, attach receipt of reimbursement made to customer for the initial invoice/costs of repair. Retroactive claims without these items will be denied.

Warranty

The emissions warranty will cover the repair costs for any failure of an emissions-related part described in this bulletin that results under normal use and service, caused by a warrantable failure, which must be the result of a defect in material and/or factory workmanship. Reimbursement will include:

- Parts
- Labor
- Consumables (when not reusable)

| |
|-----------------------------------------------------------------------------------------------|
|  NOTE |
| Cummins-powered chassis do not have Extended Emissions Coverage under this bulletin. |

PROACTIVE REPAIRS ARE NOT COVERED BY THIS PROGRAM

Towing will only be covered if 'engine' emission component failure occurs within the base engine period of 24 months/250,000 miles/6,250 hours. Outside of base engine coverage, towing and travel are excluded. PACCAR will pay for reasonable labor costs for engine removal and reinstallation when necessary to repair a warrantable failure.

The emissions warranty is retroactive and applies to qualifying warrantable failures that customers have

already had repaired at their expense.

Components that qualify for coverage on MY2021 PACCAR MX Engines:

| Engine Model Year | PPD Part Number | Part Description |
|-------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| 2021B (MX-13) | 2314737 (PEX) ⁽¹⁾ 2383579 (PEX) ⁽¹⁾ 2394548 (PEX) ⁽¹⁾ 2403201 (PEX) ⁽¹⁾ 2403776 (PEX) ⁽¹⁾ 2403778 (PEX) ⁽¹⁾ 2423652 (PEX) ⁽¹⁾ 2423654 (PEX) ⁽¹⁾ 2426854 (PEX) ⁽¹⁾ 2426856 (PEX) ⁽¹⁾ 2428774 (PEX) ⁽¹⁾ 2429855 (PEX) ⁽¹⁾ 2452062 (PEX) ⁽¹⁾ 2460410 (PEX) ⁽¹⁾ 2460412 (PEX) ⁽¹⁾ 2460414 (PEX) ⁽¹⁾ 2434417 (PEX) ⁽²⁾ 2461236 (PEX) ⁽²⁾ 2477785 (PEX) ⁽²⁾ 2477787 (PEX) ⁽²⁾ 2477863 (PEX) ⁽²⁾ 2477865 (PEX) ⁽²⁾ 2491047 (PEX) ⁽²⁾ | Fuel Injector |
| 2021B (MX-11) | 2314736 (PEX) ⁽¹⁾ 2383578 (PEX) ⁽¹⁾ 2394547 (PEX) ⁽¹⁾ 2403200 (PEX) ⁽¹⁾ 2403775 (PEX) ⁽¹⁾ 2403777 (PEX) ⁽¹⁾ 2423651 (PEX) ⁽¹⁾ 2423653 (PEX) ⁽¹⁾ 2426853 (PEX) ⁽¹⁾ 2426855 (PEX) ⁽¹⁾ 2428773 (PEX) ⁽¹⁾ 2429854 (PEX) ⁽¹⁾ 2452061 (PEX) ⁽¹⁾ 2460409 (PEX) ⁽¹⁾ 2460411 (PEX) ⁽¹⁾ 2460413 (PEX) ⁽¹⁾ 2434418 (PEX) ⁽²⁾ 2461235 (PEX) ⁽²⁾ 2477784 (PEX) ⁽²⁾ 2477786 (PEX) ⁽²⁾ | Fuel Injector |

| | | |
|------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|--|
| | 2477862 (PEX) ⁽²⁾ 2477864 (PEX) ⁽²⁾ 2491046 (PEX) ⁽²⁾ | |
| | | |
| <p>(1) Component added in previous Extended Warranty Coverage update.</p> <p>(2) Additional component added to Extended Warranty Coverage.</p> | | |

Attachments

[CE030 PB Chassis List](#)

[CE030 MX Component Specific Emissions Extended Warranty for EMY2021 PACCAR MX-11 and MX-13 Engines US Customer Letter](#)

[CE030 MX Component Specific Emissions Extended Warranty for EMY2021 PACCAR MX-11 and MX-13 Engines US Customer Letter – Spanish](#)

[CE030 MX Component Specific Emissions Extended Warranty for EMY2021 PACCAR MX-11 and MX-13 Engines CAN Customer Letter](#)

[CE030 MX Component Specific Emissions Extended Warranty for EMY2021 PACCAR MX-11 and MX-13 Engines CAN Customer Letter – French](#)



Peterbilt Motors Company
 Customer Service Department
 C/O PACCAR Parts
 750 Houser Way North
 Renton, WA 98057
 (425) 828-5888

[Date]

Subject: CE030: MX Component Specific Emissions Extended Warranty for
 EMY2021 PACCAR MX Engines

Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Peterbilt Customer,

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless your vehicle experiences a problem.

This letter has been sent to inform you that Peterbilt Motors Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. **No action is needed on your part.**

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty (EWC Code 9480835)

| Part Name | Part Number | Result of Failure |
|------------------------------|------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| Fuel Injector (MX-13, EPA21) | 2314737 (PEX) ⁽¹⁾ | Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning. |
| | 2383579 (PEX) ⁽¹⁾ | |
| | 2394548 (PEX) ⁽¹⁾ | |
| | 2403776 (PEX) ⁽¹⁾ | |
| | 2403201 (PEX) ⁽¹⁾ | |
| | 2403778 (PEX) ⁽¹⁾ | |
| | 2423652 (PEX) ⁽¹⁾ | |
| | 2423654 (PEX) ⁽¹⁾ | |
| | 2426854 (PEX) ⁽¹⁾ | |
| | 2426856 (PEX) ⁽¹⁾ | |
| | 2429855 (PEX) ⁽¹⁾ | |
| | 2428774 (PEX) ⁽¹⁾ | |
| | 2452062 (PEX) ⁽¹⁾ | |
| | 2460410 (PEX) ⁽¹⁾ | |
| | 2460412 (PEX) ⁽¹⁾ | |
| 2460414 (PEX) ⁽¹⁾ | | |



Peterbilt Motors Company
 Customer Service Department
 C/O PACCAR Parts
 750 Houser Way North
 Renton, WA 98057
 (425) 828-5888

| | | |
|------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| | 2434417 (PEX) ⁽²⁾ 2461236 (PEX) ⁽²⁾ 2477785 (PEX) ⁽²⁾ 2477787 (PEX) ⁽²⁾ 2477863 (PEX) ⁽²⁾ 2477865 (PEX) ⁽²⁾ 2491047 (PEX) ⁽²⁾ | |
| Fuel Injector (MX-11, EPA21) | 2314736 (PEX) ⁽¹⁾ 2383578 (PEX) ⁽¹⁾ 2394547 (PEX) ⁽¹⁾ 2403775 (PEX) ⁽¹⁾ 2403200 (PEX) ⁽¹⁾ 2403777 (PEX) ⁽¹⁾ 2423651 (PEX) ⁽¹⁾ 2423653 (PEX) ⁽¹⁾ 2426853 (PEX) ⁽¹⁾ 2426855 (PEX) ⁽¹⁾ 2429854 (PEX) ⁽¹⁾ 2428773 (PEX) ⁽¹⁾ 2452061 (PEX) ⁽¹⁾ 2460409 (PEX) ⁽¹⁾ 2460411 (PEX) ⁽¹⁾ 2460413 (PEX) ⁽¹⁾ 2434418 (PEX) ⁽²⁾ 2461235 (PEX) ⁽²⁾ 2477784 (PEX) ⁽²⁾ 2477786 (PEX) ⁽²⁾ 2477862 (PEX) ⁽²⁾ 2477864 (PEX) ⁽²⁾ 2491046 (PEX) ⁽²⁾ | Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning. |
| ⁽¹⁾ Components that were included in a previous letter. ⁽²⁾ Additional component added to Extended Warranty Coverage. | | |

If you have previously paid to replace any of the components listed in the table above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Peterbilt



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest Peterbilt dealer, please scan the QR code at the top of this letter or use Find a Dealer at www.Peterbilt.com. When contacting your selected dealer, refer to Extended Warranty Code (EWC) **9480835** and the VIN listed below or on the back of this letter.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.

Sincerely,

Peterbilt Customer Service



Peterbilt Motors Company
 Customer Service Department
 C/O PACCAR Parts
 750 Houser Way North
 Renton, WA 98057
 (425) 828-5888

[Date]

Subject: CE030: MX Component Specific Emissions Extended Warranty for
 EMY2021 PACCAR MX Engines

Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Peterbilt Customer,

This notice is sent to you in accordance with the requirements of the Canadian Environmental Protection Act, 1999.

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless your vehicle experiences a problem.

This letter has been sent to inform you that Peterbilt Motors Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. **No action is needed on your part.**

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty (EWC Code 9480835)

| Part Name | Part Number | Result of Failure |
|------------------------------|------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| Fuel Injector (MX-13, EPA21) | 2314737 (PEX) ⁽¹⁾ | Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning. |
| | 2383579 (PEX) ⁽¹⁾ | |
| | 2394548 (PEX) ⁽¹⁾ | |
| | 2403776 (PEX) ⁽¹⁾ | |
| | 2403201 (PEX) ⁽¹⁾ | |
| | 2403778 (PEX) ⁽¹⁾ | |
| | 2423652 (PEX) ⁽¹⁾ | |
| | 2423654 (PEX) ⁽¹⁾ | |
| | 2426854 (PEX) ⁽¹⁾ | |
| | 2426856 (PEX) ⁽¹⁾ | |
| | 2429855 (PEX) ⁽¹⁾ | |
| | 2428774 (PEX) ⁽¹⁾ | |
| | 2452062 (PEX) ⁽¹⁾ | |
| 2460410 (PEX) ⁽¹⁾ | | |



Peterbilt Motors Company
 Customer Service Department
 C/O PACCAR Parts
 750 Houser Way North
 Renton, WA 98057
 (425) 828-5888

| | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| | 2460412 (PEX) ⁽¹⁾ 2460414 (PEX) ⁽¹⁾ 2434417 (PEX) ⁽²⁾ 2461236 (PEX) ⁽²⁾ 2477785 (PEX) ⁽²⁾ 2477787 (PEX) ⁽²⁾ 2477863 (PEX) ⁽²⁾ 2477865 (PEX) ⁽²⁾ 2491047 (PEX) ⁽²⁾ | |
| Fuel Injector (MX-11, EPA21) | 2314736 (PEX) ⁽¹⁾ 2383578 (PEX) ⁽¹⁾ 2394547 (PEX) ⁽¹⁾ 2403775 (PEX) ⁽¹⁾ 2403200 (PEX) ⁽¹⁾ 2403777 (PEX) ⁽¹⁾ 2423651 (PEX) ⁽¹⁾ 2423653 (PEX) ⁽¹⁾ 2426853 (PEX) ⁽¹⁾ 2426855 (PEX) ⁽¹⁾ 2429854 (PEX) ⁽¹⁾ 2428773 (PEX) ⁽¹⁾ 2452061 (PEX) ⁽¹⁾ 2460409 (PEX) ⁽¹⁾ 2460411 (PEX) ⁽¹⁾ 2460413 (PEX) ⁽¹⁾ 2434418 (PEX) ⁽²⁾ 2461235 (PEX) ⁽²⁾ 2477784 (PEX) ⁽²⁾ 2477786 (PEX) ⁽²⁾ 2477862 (PEX) ⁽²⁾ 2477864 (PEX) ⁽²⁾ 2491046 (PEX) ⁽²⁾ | Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning. |
| <p>⁽¹⁾ Components that were included in a previous letter. ⁽²⁾ Additional component added to Extended Warranty Coverage.</p> | | |



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

If you have previously paid to replace any of the components listed in the table above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Peterbilt dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest Peterbilt dealer, please scan the QR code at the top of this letter or use Find a Dealer at www.Peterbilt.com. When contacting your selected dealer, refer to Extended Warranty Code (EWC) **9480835** and the VIN listed below or on the back of this letter.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.

Sincerely,

Peterbilt Customer Service