



Bulletin Category: Service Advisory

Business Unit: HEIL

Bulletin Number: SB-26-353

Release Date: 06/25/2026

Affected Products: RevAMP® Electric Automated Side Loader

To: Heil Dealers and Heil Customer Care

Subject: Electric Body Decommissioning & Recommissioning Procedure Updates

ISSUE / INFORMATION:

Due to incompatibility with the RevAMP body, the VeriSafe Absence Voltage Tester (AVT) was removed from multiple electric vehicle chassis variants. The removal of the AVT required revisions to the Electric Body Decommissioning and Recommissioning Procedure. Refer to the updated process outlined in the RevAMP Service Manual, TP1REV-SM-0226 (effective February 2026 and later), to ensure safe and reliable operation of your unit.

ACTION:

1. Electric Body Decommissioning and Re-commissioning:
 - Refer to the General Information Section, *Electric Body Decommissioning*, pages 18 – 25.
 - Refer to the General Information Section, *Electric Body Re-commissioning*, pages 26 – 32.

If you have any questions regarding the information detailed in this bulletin, please contact **Heil Technical Service** at **800-528-5308, option 6**.