

 Preview Solution CBR-2592-1

Fault P107B86 Accompanied With Intermittent Loss of Throttle - AN - GR - LR - PI - TE - VN - VNM - VHD

Published 22 June 2026

Valid For

Mack Chassis - AN, GR, LR, PI, TE

Volvo Chassis - VN, VHD, VNM, VNX

Model Year - 2024 to Current

The purpose of this CBR is to provide steps on how to correct a customer complaint of DTC P107B86 accompanied With intermittent loss of throttle.

Units experiencing a customer complaint of intermittent loss of throttle with transmission DTC P107B86 will need to update to the latest and greatest VECU available software. If this situation is experienced in operation a key cycle will return throttle functionality and unit can be operated.

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article