

2025 MY Ranger

Body Control Module - BCM

BCM-26.5.3

Safety Recall 26S29

Body Control Module

To view your past software updates, or if you've had multiple updates completed recently, visit: <https://www.ford.com/support/software-updates>

1

BCM-26.5.3

We have updated your vehicle's Body Control Module (BCM). Your vehicle's right or left sun visor and headliner wiring harnesses may have a pinched wire, which could result in flickering or inoperative sun visor mirror lights and overhead console lights. If the wire shorts, heat or spark from the short can cause smoke, burning, melting, or fire in the area where the sun visor meets the headliner. This update completes Safety Recall 26S29. If the sun visor mirror lights and overhead console lights are inoperative after this update, an additional repair at your dealer will be required.