

June 30, 2026

Version 2

Warranty Extension: Customer Support Program For Front Passenger's Airbag Inflator for 2003-06 Element, 2002 Odyssey, and 2003-04 Pilot (Expired June 30, 2026)

The warranty coverage under this extension expired on June 30, 2026. Repair orders dated on or prior to June 30, 2026 remain eligible and should reference the warranty claim information below.

APPLIES TO

Year	Model	Trim	VIN Range
2003-06	Element	ALL	Check the iN VIN status for eligibility.
2002	Odyssey	ALL	Check the iN VIN status for eligibility.
2003-04	Pilot	ALL	Check the iN VIN status for eligibility.

WARRANTY CLAIM INFORMATION

- To avoid non-payment of warranty claims, the new airbag module part number and serial number must be included in each claim. For more information, refer to step of REPAIR PROCEDURE.
- To avoid a warranty claim being charged back to your dealership, follow the normal warranty part retention rules. American Honda may call in the original airbag module.
- The serial number is encoded into the bar code label attached to the outside of the box. If your dealership uses a scanner, you can scan the serial number into the claim.
- The part number is encoded into a barcode attached to the outside of the box. If your dealership uses a scanner, you can scan the part number into the claim.
- If you confuse the serial number and part number when entering the claim information, your claim will automatically be rejected.**
- You must enter a DTC in the DTC field of the warranty claim.
- The FRT includes time for the inspection and replacement of the airbag module.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Failed Part Number
7541D7	2003-06 Element	0.6 hr	6A200	Z1500	06780-SCV-A21ZA
7541D7	2002 Odyssey	0.7 hr	6A200	Z1500	06780-S0X-A20ZA
7541D7	2003-04 Pilot	0.8 hr	6A200	Z1500	06780-S9V-A20ZC

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.