

Subject: UPDATED SOFTWARE RELEASE FOR CONCERNS WITH MAZDA CONNECT INFOTAINMENT SYSTEM (CX-90 WITH NA13)	Bulletin No.: 16-006/26
	Last Issued : 06/29/2026

BULLETIN NOTES

APPLICABLE MODEL(S)/VINS

2026 CX-90

DESCRIPTION

The release notes outlined below provide an overview of bug fixes, feature improvements, and updates included in the latest software release. The latest version of software contains all the updates of the previous versions.

NOTE: If current version is not 7230C1A-NA13_**, this TSB is not applicable.**

Version 7230C1A-NA13_10020 enables termination of connected services at customer request:

- Termination of Connected Services by customers at their initiative has been enabled. Accordingly, the following items have been updated.
 - Add a "Data Communication Information" item under Settings > System Settings>Online Connectivity.
 - Updated the text displayed on the confirmation screen for disabling Connected Services.

Trademarks

- iPhone and Apple CarPlay® are trademarks of Apple Inc., registered in the U.S. and other countries and regions.
- Android™ and Android Auto™ are registered trademarks of Google LLC.
- The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc.
- Amazon, Alexa and all related logos are trademarks of Amazon.com, Inc. or its affiliates.
- SIRIUSXM® is a trademark of Sirius XM Radio Inc.

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify the customer concern.
2. Update MAZDA CONNECT with software version 7230C1A-NA13_10020 or later with a USB memory stick using the 7TH GEN MAZDA CONNECT Update Instructions.

CAUTION: More than one software version can be placed on a memory stick, but Mazda recommends placing only one version on a memory stick to avoid updating the system with the wrong version.

3. Verify the repair.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

WARRANTY INFORMATION**NOTE:**

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	64
Damage Code	9W
Part Number Main Cause	5555-RP-CMU
Quantity	0
Operation Number / Labor Hours:	XXX73XFX / 0.3 Hrs.

NOTE: Keep record of successful reprogramming by taking a picture of the Mazda Connect display, showing the actual software version.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.