

| | | | | | |
|---------------------------|--|--------------|---------------|--|---|
| REFERENCE: | TSB: 09-012-26 GROUP: 09 - Engine | Date: | June 16, 2026 | REVISION: | — |
| VEHICLES AFFECTED: | 2026 (DT) RAM 1500 Pickup 2026 (WS) Grand Wagoneer/Wagoneer This bulletin applies to vehicles built on or after March 26, 2026 (MDH 0326XX) and on or before April 15, 2026 (MDH 0415XX) Equipped with the 3.0L I6 Hurricane SO Twin Turbo ESS (Sales Code EFH) . | | | MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> EE <input type="checkbox"/> IAP <input type="checkbox"/> SA <input type="checkbox"/> CH NOTE: This bulletin applies to North America markets. | |
| CUSTOMER SYMPTOM: | Customers may experience the following: <ul style="list-style-type: none"> • 'Low Oil Level' message on in the Instrument Panel Cluster (IPC). • Oil Leak. | | | | |
| CAUSE: | Casting Issue | | | | |

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-112, date of issue June 16, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves replacing the engine oil pan.

CLAIMS DATA:

| Labor Operation No: | Labor Description | Skill Category | Labor Time |
|---------------------|---|-----------------------------------|------------|
| 09-60-01-98 | Pan, Engine Oil -Replace DT (1 - Semi-Skilled) | 1 - Engine Repair and Performance | 3.0 Hrs. |
| 09-60-01-99 | Pan, Engine Oil -Replace WS (1 - Semi-Skilled) | 1 - Engine Repair and Performance | 3.1 Hrs. |
| Failure Code | ZY | Service Action | |

SPARE PARTS:

| Qty | Part No. | Description | Notes |
|-----|------------|---|--|
| 1 | 68359141AG | Oil Pan Assembly | – |
| 8 | 68523969AA | 0W-20 Full Synthetic Engine Oil | |
| 2 | 06506557AA | NUT AND WASHER, Hex Lock, M14x1.50 | (Upper Ball Joint Nut) |
| 4 | 06506497AA | BOLT, Hex Flange Head Locking | (Driveshaft To Front Axle Flange Bolts) |
| 1 | 06508531AA | SCREW, Hex Flange Head, M10x1.50x39.00 | Intermediate Shaft to Steering Gear (Steering Gear Pinch Bolt) |
| 2 | 06513404AA | NUT, Hex Lock, M12X1.25X22.00 | (Halfshaft Hub Nut) |
| 2 | 06513461AA | NUT, Outer Ball Stud to Front Knuckle | (Tie Rod End Nut) |
| 0.2 | 04883971AC | Engine Sealant RTV Silicone Rubber Adhesive | (Quantity as needed probably 1 per 5 VINs both WS and DT use it) |
| 2 | 06510880AA | Screw | |

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. **This RSU only applies to vehicles on the RSU VIN list.**

REPAIR PROCEDURE:

1. Replace the engine oil pan. Refer to the detailed service procedures listed in DealerCONNECT>Service Library>Service Info>under: 09 - Engine, 3.0L GMET6 / Lubrication / Pan, Oil / Removal and Installation.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.