

**Technical Service Bulletin (TSB)**  
**Body Control Module (BCM) Missing Generic Flash Support**

<b>REFERENCE:</b>	<b>TSB:</b> 08-251-26 <b>GROUP:</b> 08 - Electrical	<b>Date:</b>	June 27, 2026	<b>REVISION:</b>	—
<b>VEHICLES AFFECTED:</b>	2024 - 2026 (GC) Alfa Romeo Tonale 2024 - 2025 (GG) Dodge Hornet			<b>MARKET APPLICABILITY:</b> <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH <b>NOTE:</b> This bulletin applies to the North America market.	
<b>CUSTOMER SYMPTOM:</b>	<b>Technicians may experience the following:</b> <ul style="list-style-type: none"> <li>After replacing the BCM, a flash file does not appear / display in wiTECH.</li> </ul>				
<b>CAUSE:</b>	<b>BCM Generic Flash</b>				

**DISCUSSION:**

This Information Only bulletin contains information helpful or useful for technicians in diagnosing. Engineering is currently in the process of completing the release process for generic support. After replacing the BCM, if a flash file is not displayed in wiTECH please reach out to Technical Support for further assistance.

**POLICY:**

Information Only.