

GPOP - Issue Review System

Part Number: 68675802A\$, 68675807A\$, 68727385A\$, 68727386A\$

Part Description: Receiver Module

Issue WL:

Description: Dealer cannot perform programming new keyfob or re-programming existing keyfob. While programming a new keyfob (or) re-programming an existing keyfob, If the technician presses the keyfob for longer time causing multiple blinks on the keyfob can lead to programming failure. Tech to press keyfob only once until they observe single blink on the keyfob to allow keyfob the programming to be completed.