

WST X-Series Hood Cracks

COMMUNICATION:

FIELD SOLUTION: Fix as Fail

PUBLISH DATE: N/A

TOPIC BACKGROUND:

PRIMARY EFFECT:

- Customers discover cracks at hood strut mounting point inside the hood at 30000 miles plus, worsening with time.

AFFECTED MODELS:

- X Series WST

VISUALIZATION:



PROGRESS UPDATES:

- Standoffs added to the hood panel to prevent excessive adhesive squeeze-out
- Camera system on order to monitor for proper adhesive application

TOPIC RESOLUTION INFORMATION:

PRODUCTION CHANGEOVER WEEK/MONTH:

- Standoffs added to molds. Complete May 2026
- Camera monitoring system scheduled for July 2026.

RESOLUTION:

