



Technical Service Bulletin

Technical Service Bulletin: TSB260078

Released Date: 02-Jun-2026

Engine Misfire Fault Codes with No Driveability Issues

Engine Misfire Fault Codes with No Driveability Issues

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B6.70 CM3580 B193B

Issue Summary

Symptom:

- Following fault codes present with no drivability issues (SPN-FMI):
- 1322|11 (FC5914)
- 1323|11 (FC5895)
- 1324|11 (FC5896)
- 1325|11 (FC5897)
- 1326|11 (FC5898)
- 1327|11 (FC5899)
- 1328|11 (FC5911)

Root Cause:

- Low battery voltage
- Engine Control Module (ECM) calibration Tuning

Verification

Verify no drivability issues were detected.

Check if any of the symptom SPN-FMIs are active.

Resolution

This is a known fault condition with this architecture that will be resolved in a future calibration release.

Document History

Date	Details
2026-5-29	Module Created

Last Modified: 02-Jun-2026
