



Connection offline

Technical Service Bulletin

Transaction No.: **2079416/6**

91 Service info: central overview of MIB3 combined software update CL3B+ for
MLB/MQB - after UNECE deployment

Release date: Jun 22, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A3, S3, RS 3, and Q3	2024 – 2025	All	CI3A/3B 005F – Information electronics 1 Software version: 41* 4318 4364
A7, S7, RS 7, A8, S8, Q7, SQ7, Q8 SQ8, and RS Q8	2023 – 2025	All	MLB evo2 with CI39 Without PR Code: B36 005F – Information electronics 1 Software version: 40* 4404
A6, A6 allroad, S6, RS 6 Avant, e-tron GT, and RS e-tron GT	2024 – 2025		
Q8 e-tron, SQ8 e-tron, Q8 Sportback e-tron, and SQ8 Sportback e-tron	2024		
A4, A4 allroad, S4, A5, A5 Cabriolet, S5, S5 Cabriolet, RS 5, RS 5 Sportback, Q5, Q5 e quattro, Q5 Sportback, SQ5, and SQ5 Sportback	2024	All	MLB evo1 High CI39 Without PR Code: B36 005F – Information electronics 1 Software version: 40* 42* 4404
A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, e-tron GT, RS e-tron GT, Q7, SQ7, Q8, SQ8, and RS Q8	2025	All	MLB evo2 with CI3B 005F – Information electronics 1 Software version: 42* 43*
A4, A4 allroad, S4, A5 Sportback, S5 Sportback, RS 5 Sportback, Q5, Q5 e quattro, Q5 Sportback, SQ5, and SQ5 Sportback	2025	All	MLB evo1 High with CI3B 005F – Information electronics 1 Software version:

REVISION HISTORY		
Revision	Date	Purpose
6	-	Revised title (Updated title) Revised <i>Service</i> (Updated verbiage)
5	06/02/2026	Revised header (Added A3 TSB)
4	02/17/2026	Revised <i>Service</i> (Updated ETA for MQB)

Customer states:

Various complaints regarding infotainment and connectivity.

Workshop findings:

Another TSB refers you to this one for an overview of the upcoming customer service updates.

Technical Background

The service info provides an overview of the customer service packages for MLB and MQB vehicles equipped with the MIB3 system. Depending on the vehicle model, the following control units may be updated as part of a customer service package:

Diagnostic address	Control unit name
0x005F	Control unit 1 for information electronics
0x0075	Emergency call module and communication unit
0x0019	Data bus diagnostic interface (gateway)
0X078E	Android control unit 2 (fitted on vehicles with PR number IU4)



Diagnostic address 078E is a sub-node of address 005F and is therefore not shown in the control unit overview.

Proceed as follows to determine the software version of the Android control unit:

1. Flash mode.
2. SVM – Authorized Multiple Code Entry.
3. Enter **DUCIDENT005F** as the code.
4. Answer the question about sub-nodes with “yes”.

5. Click through to the sub-node with the system name “Android control module”.
6. Read software version.

Production Solution

This is software for service work. No deployment in series production.

Service

If directed to this TSB from another referring TSB, please update the vehicle using the table below:

Vehicle Platform	Customer service package
MLB Gen1 (A4, A5, Q5)	TSB 2079671, 91 Software update for MMI, connectivity box for MIB3 vehicles (version MLB G1 ST3BP with AED). TSB 2079904, 91 Software update for MMI, connectivity box for MIB3 vehicles (version MLB G1 ST3BP without GW + AED) TSB 2079813, 91 Software update for MMI, connectivity box for MIB3 vehicles (version MLB G1 ST3BP without GW without AED) TSB 2079670, 91 Software update for MMI, connectivity box for MIB3 vehicles (version MLB G1 ST3BP without AED)
MLB Gen2 (A6, A7, A8, Q7, Q8)	TSB 2079681, 91 Software update for MMI, connectivity box for MIB3 vehicles (version MLB G2 ST3BP with AED) TSB 2079680, 91 Software update for MMI, connectivity box for MIB3 vehicles (version MLB G2 ST3BP without AED)
e-tron GT	TSB 2079979, 01 MMI software update, connectivity box for MIB3 vehicles (version MLB e-tron GT ST3BP without AED) TSB 2079980, 91 MMI software update, connectivity box for MIB3 vehicles (version MLB e-tron GT ST3BP with AED)
MQB (A3, Q3)	TSB 2081007, 91 Software update for MMI, OCU and gateway for MIB3 vehicles (version MQB ST3BP without AED) TSB 2082222, 91 Combined software update, MIB3 infotainment 3BP KD+AED / MQB

Warranty

Billing via this service info is not permitted. Billing can only take place once the updates have been issued. You can find warranty accounting instructions in the TSB with the applicable update instructions.

Additional Information

All part and service references provided in this TSB (**2079416**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or

otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.