



Connection offline

Technical Service Bulletin

Transaction No.: **2080373/2**

34 Uncomfortable gear shifts when shifting in higher gears

Release date: Jun 25, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
Q3	2020 – 2022	All	PR Code: 0EW

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Add Model Years)
1	12/09/2025	Initial publication

Customer statement:

- Uncomfortable gear shifts when shifting up from 5th to 6th gear.

and/or

- Uncomfortable gear shifts when shifting up from 6th to 7th gear.

and/or

- Uncomfortable gear shifts when shifting up from 7th to 8th gear.

Workshop findings:

- No relevant event memory entries in diagnostic address 0002.

Technical Background

Optimized ignition timing during upshifts.

Production Solution

Implemented in MY23.

Service



NOTICE

Always use DoIP when flashing a control module via ODIS in supported vehicles.

- **To activate DoIP, select *Administration > General > GFF Process > DoIP communication > Only allow DoIP communication*.**
- **This setting will automatically reset when the diagnostic session has ended. You can tell if DoIP is active by observing a red LED on the VAS 6154 (A).**

Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.

Update the engine control unit (diagnostic address 0001) using the **SVM code 01A320**.

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0041		
Labor Operations:	Software update	0151 0010	See SRT with associated operations
	Software update	0151 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2080373/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations as well as any associated tasks.

Additional Information

All part and service references provided in this TSB (**2080373**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.