

Vehicle-specific service

Transaction No.: **2082262/1**

43 PSS Drive system fault (P060C00 Symptom 376838) in J1313 (diagnostic address 812C)

Release date: Jun 18, 2026

Condition


Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A5, S5 (FU), Q5, Q5 Sportback, SQ5, and SQ5 Sportback (GU)	2025 – 2026	All	Not applicable
A6	2026		

Customer states:

The message “Drive system: fault. Limited performance” appears in the instrument cluster.

Workshop findings:

The entry **P060C00** with symptom number 376838 is logged in diagnostic address 812C and the recorded ambient conditions (date and time) match those experienced by the customer.



Postpone repair

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

If further relevant DTCs are logged in diagnostic addresses 812C and/or 0001 in accordance with the description of the customer's experience, these DTCs must be worked through via Guided Fault Finding.

If only the DTC **P060C00** with symptom 376838 in address 812C is relevant to the customer complaint, **please postpone the repair**. A combined software update is currently being implemented. It will be rolled out in stages for the different models and markets. All information about the current schedule and availability of the measure can be found in the central service info TSB 2081477, *00 Service info: central overview of combined software update 03.11.00/C PPE/PPC - KD2**.

This complaint is solved in **VR target state 03.20.00/C [KD3]**. Please check the column **VR target state 03.20.00/C [KD3]** in the central service info **TSB 2081477, 00 Service info: central overview of combined software update 03.11.00/C PPE/PPC - KD2***.

You can find information about the schedule for the introduction of the measure there.

As part of the process, create a PSS record in the PSS database via the Pending Service Solutions (PSS) link found in Audi Now; *Service | AU-US > Pending Service Solutions (PSS)*.

Warranty

There is no reason to replace parts or attempt repairs. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4316		
Damage Code:	0039		
Labor Operations:	GFF/Guided Functions	0150 0010	See SRT with associated operations
	GFF/Guided Functions	0150 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2082262/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*.

Claims are subject to review or audit by Audi Warranty.

Try to reproduce the customer complaint (based on the description/cause of the issue), so that it can be clearly assigned to this TSB. The following repair must only be carried out if all the criteria (model/type, chassis number, engine/motor, gearbox code, PR number(s), part number, software version, code, etc.) apply exactly. Otherwise, this solution will not eliminate the problem and repeat repairs may be necessary. In such a case, the warranty claim may be rejected, and the cost of the parts may be charged back.

Additional Information

All part and service references provided in this TSB (**2082262**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America LLC / Audi Canda, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.