

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
S5 (FU), SQ5, and SQ5 Sportback (GU)	2025 – 2026	All	Engine type DWVA
A6	2026		


Customer statement:

Drive system fault (EPC) active in instrument cluster.

Workshop findings:

The following event memory entry is logged in diagnostic address 0001:

- **P060C00** Internal Control Module Main Processor Performance – **symptom 45618**



Documentation required

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

Please open a ticket with the Technical Assistance Center (TAC).

Please use the following workshop code: Engine → Actuation, engine control → Engine control unit

Describe the customer complaint as exactly as possible and document it with photos if appropriate. Please attach precise photos/videos for visual complaints.

When billing, please always attach a photo that clearly shows the complaint to Doc-IT.

To ensure a reference to the vehicle, the photo must include the chassis number and the date.

The photo must not be edited. The photo should be in focus and be taken with sufficient light. A high resolution is not necessary.

If appropriate, please mark the location of the problem so that parts analysis have a clear reference to the complaint.

Please ensure that the photo documentation does not show any persons and/or faces, vehicle registration numbers (number plates) or customer data.

If you do not receive a reply from TAC within two hours, perform the necessary repairs yourself.

We reserve the right to only pay out for warranty claims after thorough checks if a reporting obligation is not observed. We apologize for any inconvenience caused if delays in processing occur as a result.

Complaints already covered by a TSB in HST (ELSA) are exempt from this reporting obligation.

On behalf of Audi of America, thank you for your assistance.

Warranty

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0055		
Labor operations:	GFF/ Guided Functions	0150 0010	See SRT with associated operations
	GFF/ Guided Functions	0150 0060	Labor according to the diagnostic log
Claim Comment:	As per TSB 2082285/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations as well as any associated tasks.

Additional Information

All part and service references provided in this TSB (**2082285**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.