

- Updated BCM reflash calibration

2024-2026: CVO Road Glide ST (FLTRXSTSE)

- Updated Electronic Control Module (ECM) reflash calibration

2026: CVO Street Glide ST (FLHXSTSE)

- Updated ECM reflash calibration

Changes

2026 Trike

- Update “Reverse Lockout Reason” to support new values
- “Vehicle setup: Gear Indicator Calibration” – improve operation

2025-2026 Softail

- Update reflash for Softail Speedometer (SPDO) – enable operation of auxiliary lamp telltale

LiveWire S2

- Provide reflash support for VSC hardware (Part No. 41001756RE)

Version 26.4.3

Release Date:

- Week of February 25, 2026

New Features

Support for 2026 LiveWire Vehicles

- VINs
- Module part number identification
- Module reflash / calibration
- Module replace support
- Vehicle setup
- Guided diagnostic support

LiveWire S2

- Vehicle Status: Display notification when vehicle has unconfigured Electro Hydraulic Control Unit (EHCU) module
- Vehicle Setup: New operation to support Anti-lock Braking System (ABS) / EHCU Correction
- Reflash: Enabled EHCU calibrations for vehicles previously ineligible for update, requiring ABS / EHCU Correction to be performed

2021–2025 Pan America (RA1250), Pan America S (RA1250S), Pan America ST (RA1250ST), CVO Pan America (RA1250SE)

- Reflash – Updated ECM software calibration to improve quick shifter performance.

Changes

Infotainment Control Unit (IFCU) Customization – Correct issue where speakers were improperly configured

Version 26.3.2

Release Date:

- Week of January 28, 2026

New Features

LiveWire

- S2DM/MH/AP calibration bundle (10.2.15): VSC, OBC, RESS, TCU, BCM reflash updates

Changes

- Revolution® Max – Correct issue where ECM (Part No. 41000713) was not being offered reflash
- Improve handling of Clutch Switch Data item for ECM (Part No. 41000713)
- Added vehicle pictures to Vehicle Identification Number (VIN) selection page for 2026 models: Pan America Limited (RA1250L), Street Glide Limited (FLHXL), Road Glide Limited (FLTRXL), CVO Street Glide (FLHXSE), CVO Road Glide ST (FLTRXSTSE), CVO Street Glide ST (FLHXSTSE), Street Glide 3 Limited (FLHLT), Road Glide 3 (FLTRT) and CVO Street Glide 3 Limited (FLHLTSE)

Version 26.2.1

Release Date:

- Week of January 16, 2026

New Features

Support for 2026 Trike and Touring Vehicles

- VINs
- Module reflash / calibration
- Module replace support
- Vehicle setup
- Guided diagnostic support

2023-2025 Touring

- Updated BCM software

Changes

Revolution® Max / 2025 and later Softail Continental ABS / EHCU Service Vehicle setup

- Add 30 second delay to manual bleed step, to accommodate module specifications

2026 Touring: Guided Diagnostics – Update U0273 to inform unprogrammed module may set this Diagnostic Trouble Code (DTC)

Version 26.1.5

Release Date:

- Week of December 15, 2025

New Features

2026 Revolution® Max Vehicles (RH975, RH975S, RH1250S, RA1250S, RA1250ST)

- VINs
- Calibration support (including Michelin Anakee Wild tire selection)
- Module replace support
- Vehicle setup
- Guided diagnostic support

Changes

- Guided Diagnostics: Fixed missing 2026 Police BCM Diagnostic Trouble Code (DTC) U027300
- Vehicle Setup - Tire Pressure Monitoring System (TPMS) - Tire Selection – Add logic to confirm ECM calibration is at proper version before allowing Michelin Anakee Wild tire selection.

Version 26.0.2

Release Date:

- Week of November 18, 2025

New Features

2026 Vehicles

- Calibration support
- Module replace support
- Guided diagnostic support
- Variable Valve Timing (VVT) feature support for vehicles with Engine Character "N"
- Updated DTC support
- Support Auxiliary Load Controller (ALC) on Police vehicles
- Support 2026 IFCU speaker configurations

2025 Softail

- Updated BCM software

LiveWire: Del Mar (S2DM), Mulholland (S2MH), Alpinista (S2AP) - EV3

- Updated calibration bundle 10.1.9/10: VSC, OBC, RESS, TCU, BCM
- Features: Vehicle capability of reverse and roll-forward regen

Changes

- DT II License Error – updated text
- Advance Audio Radio Reflash – Fixed error on J1850 vehicles
- External power required for SPDO, ABS, EHCUC modules during reflash
- Ignition ON required for ECM, ALC, Heated Seat Module (HSM) modules during reflash
- Removed Vehicle Status notification to LiveWire for instrument update

System Information

- Improved load performance
- IFCU - Hide AMP2 fields when module is not present

Required Dealer Action

Techlink

- The TECHLINK 3 (PART NUMBER: HD-48650-TL3) will support CAN protocol vehicles (6-pin Data Link Connector (DLC)) at launch. J-1850 protocol (4-pin DLC) support is planned for early 2020.

- Techlink 3 will not support Harley-Davidson Buell, Vereinigte DEUTA-OTA (VDO) and Magneti Marelli vehicles (4-pin DLC). Support for those vehicles is available via TECHLINK II (PART NUMBER: HD-48650-1).
- 2021 vehicles must use TECHLINK 3 (PART NUMBER: HD-48650-TL3) (connects to Red DLC on the vehicle).

Digital Technician™ II

- The Digital Technician II software version updates are automatic and occur while connected to the Internet.
- If an internet connection is lost, the download continues from where it stopped.
- If the Digital Technician II software is open, the application prompts the user to exit before the install can continue.
- All Digital Technician II software updates are deployed automatically via the XMS agent software and require a minimum model year software version (example: Model Year 2021 = minimum version v21.0).