

Table 4. Problem Part Numbers

Model Year	Model	Part No's	Item Description
2023	FLHXSE	69202979	HARNESS WIRE, MAIN
	FLTRXSE	69202980	
2024	FLHX, FLHXSE	69202979A	
	FLTRX, FLTRXSTSE, FLTRXSE	69202980A	
	FLHX, FLHXU	69203606	
2025	FLTRX, FLTRXSTSE	69203607	
	FLHXSE	69203413	
	FLTRXSE	69203414	

Credit Procedure

NOTE

Enter bulletin number into comment section of claim.

Submit a warranty claim per Table 5.

Table 5. Ignition Coil Harness Repair

ITEM	DATA
Claim Type	PRD/MC/DEM - PDI/Standard Claim
Problem Part Number	Refer to Table 4.
Quantity	Leave Blank
Primary Labor Code ⁽¹⁾	5090
Labor Time	0.6 hours
Customer Concern Code	9203
Condition Code	4104
Replacement Part Number	69203885
Quantity	1
(1) Download may be required	

NOTE

Enter M1700 in Event Comments.