



2026-06-03



**M1730: INCORRECT DERBY COVER ON LIBERTY EDITION ROAD GLIDE (FLTRX)
AND STREET GLIDE 3 LIMITED (FLHLT)**

Refer to Table 1

Table 1. Document History

Date	Rev	Revision (Rev) Description
2026-06-03	-	Initial release

Purpose for Service Bulletin

This bulletin informs dealers that select Liberty Edition Road Glide (FLTRX) and Street Glide 3 Limited (FLHLT) motorcycles built between May 21, 2026 and June 10, 2026 **will be shipped with an Incorrect Derby Cover (Part No. 25701561) installed.** See Figure 1.

This is the result of a temporary part shortage impacting the correct Liberty Edition component. Dealers will be required to replace the incorrect Derby Cover (Part No. 25701561) and associated components with the correct Derby Cover (Part No. 25702025) and associated components once they arrive at the dealership.

Harley-Davidson will be sending the replacement parts directly to dealers with impacted units starting mid-June.

Required Dealer Action

Table 2. Required Dealer Action

Category	Description	Required
1	Must Perform Repair	☒
2	Repair If Presenting Symptom	☐
3	Feature Pack-Customer/Dealer Paid	☐
4	Informational Purposes Only	☐

Vehicles Affected

2026: Road Glide (FLTRX), Street Glide 3 Limited (FLHLT)

Markets Affected

United States and Canada only.

Affected Part Numbers

Refer to Table 3 and Table 4.

Table 3. Derby Cover Part Numbers

Installed Part No.	Item Description	Replacement Part No.
25701561	Cover, Derby	25702025

Table 4. Other Part Numbers

Part No.	Item Description	Quantity
25418-06	Gasket	1

Dealer Inventory Instructions

Replace the Incorrect Derby Cover (Part No. 25701561, Figure 1) and old gasket with the Correct Derby Cover (Part No. 25702025, Figure 2) and **new** gasket once they arrive at the dealership. See service manual.



Figure 1. Incorrect Derby Cover

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

[illegible]



2. Liberty Edition (Part No. 25702025)

Figure 2. Correct Derby Cover

Credit Procedure

NOTE

Enter M1730 in Event Comments.

Submit a warranty claim per Table 5.

Table 5. Derby Cover Replacement

ITEM	DATA
Claim Type	PRD/MC/DEM
Problem Part Number	25701561
Quantity	Leave Blank
Primary Labor Code	4001
Labor Time	0.1 hours
Customer Concern Code	6311
Condition Code	9102
Replacement Part Number	25702025: Qty 1 25418-06: Qty 1

Return Parts

Hold all claimed parts for 60 days from date of credit issued for possible field inspection and/or request to return to factory. After 60 days, destroy and discard the parts.