

Additional Test Instructions for Rim Damage on the Front Axle (53/26)

Model Line: **911 (992)**

Model Year: **As of 2025 up to 2026**

Concerns: **Front wheel suspension**

Information: **The customer complains or rim damage on the front axle is identified during a workshop visit.**

Cause: Rim damage on the front axle caused by an **impact** can also indicate damage to other chassis components.



Information

An **impact** is damage that goes beyond ordinary rim scratches due to slight contact with the curb.

Action: As soon as rim damage is identified on the front axle, **always** carry out a check and damage assessment of the chassis components in accordance with the Workshop Manual.
 ⇒ *Workshop Manual '4005IN'* Front wheel suspension (damage assessment after accident or impact) Information

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2026 Porsche Cars North America, Inc.