

D123 – CAR CONFIGURATION FILE UPDATE

SERVICE ACTION



AFFECTED MODELS	26MY Range Rover, Range Rover Sport
VOLUME AFFECTED	1427 US 69 Canada
REPAIR	A concern has been identified on certain 2026 model year Range Rover and Range Rover Sport vehicles, where the Driver Condition Monitor (DCM) feature is not selectable on the Interactive Display Module 'A' (IDMA). . Affected vehicle require an update to the Car configuration file to correct this
REPAIR TIME	0.2 - 0.3hrs+ DIDO
CAMPAIGN LAUNCH	Repair bulletin published May 21 st , 2026
NOTES	Retailers are required to hold from sale, all new affected vehicles in their inventory until the repair is completed. All affected VINs are flagged in TOPIx, the warranty portal and retailer inventory reports are available in BBSS. As of June 9th, 2026, 86 affected USA new vehicles remain in retailer inventory.