

D134 – L461/L460 PHEV BECM EU SANCTIONS - BECM SEMICONDUCTORS

QUARANTINE



AFFECTED MODELS	26MY Range Rover and Range Rover Sport
VOLUME AFFECTED	355 US 62 CAN
REPAIR	Vehicles will require the replacement of the BECM module. This is housed within the PHEV HV battery requiring a lid-off repair.
REPAIR TIME	Est 6.4 hrs +DIDO
CAMPAIGN LAUNCH	Quarantine Bulletin published June 3 rd , 2026 Repair bulletin is TBC when sufficient parts are available.
NOTES	Retailers are required to hold from sale, all affected vehicles in their inventory until the repair can be completed. All affected VINs are flagged in TOPIx, the warranty portal and retailer inventory reports are available in BBSS. BBSS shows 31 US and 1 Canadian vehicles under retailer control as of June 3 rd , 2026. A VIN list was also shared with the retailer network.